

Inspection Photos
Location Name: Kennedy 18-D Pad
Location ID: 439079



September 22, 2025 at 3:51 PM
+40.317774, -105.037006
209° SW
Weld County
Energy & Carbon Management Commission



September 22, 2025 at 3:51 PM
+40.317774, -105.037006
209° SW
Weld County
Energy & Carbon Management Commission

Sign

Location

Inspection Photos
Location Name: Kennedy 18-D Pad
Location ID: 439079



Location

Wells

Inspection Photos
Location Name: Kennedy 18-D Pad
Location ID: 439079



Maintenance Tank

Sand Can

Inspection Photos
Location Name: Kennedy 18-D Pad
Location ID: 439079



Rain water in secondary containment

Liner needs fixed or replaced

Inspection Photos
Location Name: Kennedy 18-D Pad
Location ID: 439079



Location

Missing Bird protector on tank