

Inspection Photos
Location Name: Park T-4 Pad Tank Battery
Facility ID: 482414



Signs

Inspection Photos
Location Name: Park T-4 Pad Tank Battery
Facility ID: 482414



Location

Location

Inspection Photos
Location Name: Park T-4 Pad Tank Battery
Facility ID: 482414



Location

Location

Inspection Photos
Location Name: Park T-4 Pad Tank Battery
Facility ID: 482414



Compressor



Waddles

Inspection Photos
Location Name: Park T-4 Pad Tank Battery
Facility ID: 482414



Waddles and Gaslift skid



Gas Meter Run

Inspection Photos
Location Name: Park T-4 Pad Tank Battery
Facility ID: 482414



Missing Capacity label

Unused Equipment

Inspection Photos
Location Name: Park T-4 Pad Tank Battery
Facility ID: 482414



Unused Equipment “tubing”