

Inspection Photos

Operator: **LARAMIE ENERGY LLC - 10433**

Location Name: **PICEANCE 28-11 PAD**

Location ID: **438499**

Inspection Date: **9/9/2025** Inspection Doc#: **693808945**



Wellhead Location entrance with sign (damaged)



Wellheads with signs and Chemical Injectors

Inspection Photos

Operator: LARAMIE ENERGY LLC - 10433

Location Name: PICEANCE 28-11 PAD

Location ID: 438499

Inspection Date: 9/9/2025 Inspection Doc#: 693808945



Sep 9, 2025 12:03:11 PM
39.24871N 107.77911W

Production Location entrance with sign



Sep 9, 2025 12:03:45 PM
39.24834N 107.77916W

Tank Battery with metal berm

Inspection Photos

Operator: **LARAMIE ENERGY LLC - 10433**

Location Name: **PICEANCE 28-11 PAD**

Location ID: **438499**

Inspection Date: **9/9/2025** Inspection Doc#: **693808945**



Separators



Telemetry

Inspection Photos

Operator: LARAMIE ENERGY LLC - 10433

Location Name: PICEANCE 28-11 PAD

Location ID: 438499

Inspection Date: 9/9/2025 Inspection Doc#: 693808945



Pig Station



Riser (blinded)

Inspection Photos

Operator: LARAMIE ENERGY LLC - 10433

Location Name: PICEANCE 28-11 PAD

Location ID: 438499

Inspection Date: 9/9/2025 Inspection Doc#: 693808945



Riser with valves (blinded)