

Inspection Photos
Location Name: Strong (tank battery)
Location ID: 476271



Photo 1: Tank battery sign

Photo 2: Tank battery

Inspection Photos
Location Name: Strong (tank battery)
Location ID: 476271



Photo 3: overgrown vegetation

Photo 4: overgrown vegetation

Inspection Photos
Location Name: Strong (tank battery)
Location ID: 476271



Photo 5: overgrown vegetation

Photo 6: overgrown vegetation

Inspection Photos
Location Name: Strong (tank battery)
Location ID: 476271



Photo 7: overgrown vegetation

Photo 8: overgrown vegetation

Inspection Photos
Location Name: Strong (tank battery)
Location ID: 476271



Photo 9: overgrown vegetation

Photo 10: overgrown vegetation

Inspection Photos
Location Name: Strong (tank battery)
Location ID: 476271



Photo 11: overgrown vegetation

Photo 12: overgrown vegetation

Inspection Photos
Location Name: Strong (tank battery)
Location ID: 476271



Photo 13: NFA placard damaged

Photo 14: NFA placard damaged

Inspection Photos
Location Name: Strong (tank battery)
Location ID: 476271



Photo 15: NFPA placard damaged

Photo 16: No contents, capacity displayed. NFPA placard damaged