

Inspection Photos
Location Name: Totem 27
Location ID: 486777



Pic 1 drilling rig

Pic 2 posted permit

Inspection Photos
Location Name: Totem 27
Location ID: 486777



Pic 3 chemicals

Pic 4 chemicals

Inspection Photos
Location Name: Totem 27
Location ID: 486777



Pic 5 stormwater control measures

Pic 6 Stormwater erosion damage. CO man informed me they were aware and have plans to fix issue.

Inspection Photos
Location Name: Totem 27
Location ID: 486777



Pic 7 Chemicals

Pic 8 Drilling rig / location