



CEMENT | FLUID | INFRASTRUCTURE SERVICES

WWW.MAGNUMSERVICES.COM



Post Job Report

Prepared for CIVITAS RESOURCES

Grimm Motocross 4-65 23- 24 4BH

API #05-005-07573

Surface Casing Cement

July 12, 2025

Disclaimer and Confidentiality Statement

This report and all accompanying materials, are confidential and intended solely for the use of the individual or entity to whom they are addressed. The interpretations provided by the Magnum Cementing Services Technical Team are based on available data and best practices at the time of reporting. If you are not the intended recipient, you are hereby notified that any disclosure, copying, distribution, or use of this information is strictly prohibited. If you have received this report in error, please notify the sender immediately and delete it from your system. Magnum Cementing Services assumes no responsibility for decisions made based on the contents of this report. The final use and application of the information contained herein remain the sole responsibility of the Customer.

US Treatment Report



Customer: CIVITAS RESOURCES

Rep:

Supervisor: EVAN WHITE

Job Type: US Primary

Casing-Surface

Rig: Patterson 345

Well: Grimm Motocross 4-65 23-24 4BH

UWI: Grimm Motocross 4-65 23-24 4BH

Surface: Grimm Motocross 4-65 23-24 4BH

Job #: JOB00214079

Job Date: July 12, 2025

Time Requested: 18:00

Time Arrived: 17:00

Time Released: 24:00:00

1533 sk MAG S 13.3 + 0.10% MCDF-P + 1.00% MCLC-2 + 0.10% MCLC-F

Yield: 1.46 ft³/sk = 398.62bbbls Mix Water: 7.05 gal/sk = 257.33 bbl

BHCT (F)	110	BHST (F)	151	Surface Casing Size (in)	9.625
Surface Casing Grade	J-55	Surface Casing Weight (lb/ft)	36	Collapse Csg Pressure (psi)	2020
Float Depth (ft)	3569	Max Csg Pressure (psi)	3520	Max Pressure (psi)	2500
Mud Density (lb/gal)	9.3	Plug Size (in)	9 5/8	Plug Type	Rig Supplied
TMD (ft)	3614	TVD (ft)	3385		
		Total Casing (ft)	3604		

Treatment Info: Sacks Used: 1533 Sacks Not Used: 0

Preflush: 5bbbls Fresh Water & 10bbbls MAG Mark & 10bbbls Fresh Water

	Circulation Time: 0.5
	Slurry Temp: 86 Bulk Sample: Yes
	Water Temp: 75 Water Sample: Yes
	Bulk Temp: 85 Slurry Sample: Yes
	Air Temp: 80 Air Pressure
Slurry Returns: 65	Plug Bumped: Yes Pump Out Lines: No Float Held: Yes
Cement Class:	OWG Humidity: Precipitation:

Displace: 275.92bbbls Fresh Water

Further Blend Details:

Prehydrated: N/A

Additional Details (General Notes):

Time	Pressure psi	Annular Pressure psi	Volume Per Stage bbls	Total Stage Volume bbls	Rate bbls/mi n	Treatment Detail
18:00	0.00					Arrive on Location
18:45	0.00					Safety Meeting
19:16	200.00			5	4	Fill Lines - Fresh Water
19:19	1,000.00					Start Pressure Test
19:21	2,800.00					End Pressure Test
19:22	200.00			10	4	Pump Preflush - Mag Mark
19:25	200.00			10	3.5	Pump Preflush - Fresh Water
19:29	800.00			398	6.25	Pump Slurry - Mag S 13.3
20:31	0.00					Stop Pumping
20:32	0.00					Drop Plug

20:33	1,400.00		260	260	6.25	Displace - Fresh Water
21:15	1,100.00		15.92	275.92	3.5	Decrease Rate - Fresh Water
21:18	1,500.00					Bump Plug
21:19	0.00					Check Floats - 1BBL Back
21:30	0.00					Rig Out
22:00	0.00					Wash Up Truck
00:00	0.00					Leave Location



Customer: Civivtas

Date: July 12/25

Ticket: 214079

Location: Grimm Motocross 4-65 23-24 4BH

Well Name: Grimm Motocross 4-65 23-24 4BH

Job Type: Surface

Magnum Unit #: 1015

