

Inspection Photos

Loc: 485921

Operator: WAVETECH HELIUM INC

Inspection Date: 9/24/2025

County: CHEYENNE



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing east along the access road. There is water pooling on the road and vehicles are driving outside of the road causing unnecessary disturbance. The road must be constructed with BMP's.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:485921 | Date: 9/24/2025

Inspection Photos



Photo 2. Facing east along the area where vehicles are driving off the designated road causing crop damage.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:485921 | Date: 9/24/2025

Inspection Photos



Photo 3. Facing northeast along the access road toward the drill site. There is water pooling on the road which is inaccessible. There are signs of vehicles driving off the access road causing disturbance. The road needs to be constructed with BMP's.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:485921 | Date: 9/24/2025

Inspection Photos



Photo 4. Facing northeast toward the location.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:485921 | Date: 9/24/2025

Inspection Photos



Photo 5. The tank battery earthen berm is not compacted to contain a spill.



Inspection Photos



Photo 6. North side of the location facing west. The location has been recontoured but it does not appear reseeding has been performed.



Inspection Photos



Photo 7. North side of the location facing south. All unused areas of the location will need to be reclaimed.

