

# Inspection Photos

09/17/2025

**Operator:** TEP Rocky Mountain LLC #96850

**Location ID:** 437879

**Inspection Doc:** 719200243

Garfield County, CO

Emily Gaasche  
NW Reclamation Specialist  
ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 437879



**Photo 1:** Photos showing an overview of the location looking north and south, respectively.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 437879



**Photo 2:** Photos showing an overview of the location looking east and west, respectively.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 437879



**Photo 3:** Interim areas are composed of common yarrow and slender wheatgrass with secondary amounts fourwing saltbush. Interim areas are In Process.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 437879



**Photo 4:** Cheatgrass has established on the margin of the working pad surface. Weed management is required. Comply with Rule 606.c.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources