

Inspection Photos

09/17/2025

Operator: TEP Rocky Mountain LLC #96850

Location ID: 418061

Inspection Doc: 719200255

Garfield County, CO

Emily Gaasche
NW Reclamation Specialist
ECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 418061



Photo 1: Photos showing an overview of the location looking north and south, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 418061



Photo 2: Photos showing an overview of the location looking east and west, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 418061



Photo 3: Photos showing an overview of the western and eastern interim areas. Heavy cattle use is evident. Some portions of the interim areas possess perennial vegetation; however, uniformity and progression towards eighty (80) percent is not evident. Other areas remain predominantly bare. Comply with 1003 series rules and conduct additional reclamation efforts.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 418061



Photo 4: Photos showing an overview of the northern and western interim areas. Heavy cattle use is evident. Some portions of the interim areas possess perennial vegetation; however, uniformity and progression towards eighty (80) percent is not evident. Other areas remain predominantly bare. Comply with 1003 series rules and conduct additional reclamation efforts.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources