

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:

404370951

Date Received:

09/28/2025

Spill report taken by:

Spill/Release Point ID:

SPILL/RELEASE REPORT (INITIAL /w SUPPLEMENTAL)

This form is to be submitted by the party responsible for the oil and gas spill or release. Refer to ECMC Rule 912.b. for reporting requirements of spills or releases of E&P Waste, produced Fluids, or unauthorized Releases of natural gas. Submit a Site Investigation and Remediation Workplan (Form 27) if Rule 913.c. applies.

OPERATOR INFORMATION

Name of Operator: <u>HIGHPOINT OPERATING CORPORATION</u>	Operator No: <u>10071</u>	Phone Numbers
Address: <u>555 17TH ST STE 3700</u>		Phone: <u>(720) 315-8934</u>
City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>		Mobile: <u>()</u>
Contact Person: <u>Luke Kelly</u>		Email: <u>LKelly@civiresources.com</u>

Transfer of Operatorship: Pursuant to Rule 912.f, this Supplemental Form 19 is being submitted to designate the Buying Operator as the responsible Operator for this Spill and Release.

INITIAL SPILL/RELEASE REPORT

Initial Spill/Release Report Doc# 404370951

Initial Report Date: 09/28/2025 Date of Discovery: 06/15/2022 Spill Type: Historical Release

Spill/Release Point Location:

QTRQTR SESW SEC 11 TWP 6N RNG 62W MERIDIAN 6

Latitude: 40.495498 Longitude: -104.292443

Municipality (if within municipal boundaries): _____ County: WELD

Enter Lat./long measurement of the actual Spill/Release Point. Lat./Long. Data shall meet standards of Rule 216.

Check this box if this spill/release is related to a loss of integrity of a flowline, pipeline, crude oil transfer line, or produced water transfer line.

Reference Location:

Facility Type: TANK BATTERY Facility/Location ID No 422932

Spill/Release Point Name: Dutch Lake 9-11H Well API No. (Only if the reference facility is well) 05- -

No Existing Facility or Location ID No.

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): Unknown

Estimated Condensate Spill Volume(bbl): Unknown

Estimated Flow Back Fluid Spill Volume(bbl): 0

Estimated Produced Water Spill Volume(bbl): Unknown

Estimated Other E&P Waste Spill Volume(bbl): 0

Estimated Drilling Fluid Spill Volume(bbl): 0

Specify: _____

Has the subject Spill/Release been controlled at the time of reporting? Yes

Land Use:

Current Land Use: OTHER _____

Other(Specify): Range Land _____

Weather Condition: Clear _____

Surface Owner: FEE _____

Other(Specify): _____

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

During an internal review/audit of data alteration, HighPoint found data anomalies and identified that a spill should have been reported for the Dutch Lake 09-11H on 6/15/2022. HighPoint is submitting this form to establish the record of the spill, is submitting accurate lab data with the Form 27, requests reopening REM Project ID 22792, and requests closure of this spill/release under the active remediation project.

List of Agencies and Other Parties Notified Pursuant to Rule 912.b.(7)-(11):

OTHER NOTIFICATIONS

Date	Agency/Party	Contact	Phone	Response
9/28/2025	Surface Owner	on file	-on file	Notified of historic release
9/28/2025	Weld County OEM	Dave Burns	-on file	Notified via OEM report

REPORT CRITERIA

Rule 912.b.(1) Report to the Director (select all criteria that apply):

No Rule 912.b.(1).A: A Spill or Release of any size that impacts or threatens to impact any Waters of the State, Public Water System, residence or occupied structure, livestock, wildlife, or publicly-maintained road.

Waters of the State: _____ Public Water System: _____

Residence or Occupied Structure: _____ Livestock: _____

Wildlife: _____ Publicly-Maintained Road: _____

No Rule 912.b.(1).B: A Spill or Release in which 1 barrel or more of E&P Waste or produced fluids is spilled or released outside of berms or other secondary containment.

No Rule 912.b.(1).C: A Spill or Release of 5 barrels or more of E&P Waste or produced Fluids regardless of whether the Spill or Release is completely contained within berms or other secondary containment.

No Rule 912.b.(1).D: Within 6 hours of discovery, a Grade 1 Gas Leak. For a Grade 1 Gas Leak from a Flowline, the Operator also must submit the Form 19 – Initial, document number on a Form 44, Flowline Report, for the Grade 1 Gas Leak

Enter the approximate time of discovery _____ (HH:MM)

Enter the Document Number of the Grade 1 Gas Leak Report, Form 44 _____

Was there a reportable accident associated with either a Grade 1 Gas Leak or an E&P waste spill or release? _____

Enter the Document Number of the Initial Accident Report, Form 22 _____

Was there damage during excavation? _____

Was CO 811 notified prior to excavation? _____

Yes Rule 912.b.(1).E: The discovery of 10 cubic yards or more of impacted material resulting from a current or historic Spill or Release. Discovery and reporting will not be contingent upon confirmation samples demonstrating exceedance of Table 915-1 standards.

Estimated Volume of Impacted Solids (cu. yd.): _____ 20

No Rule 912.b.(1).F: The discovery of impacted Waters of the State, including Groundwater. Discovery and reporting will not be contingent upon confirmation samples demonstrating exceedance of Table 915-1 standards. The presence of free product or hydrocarbon sheen on Groundwater or surface water is reportable. The presence of contaminated soil in contact with Groundwater or surface water is reportable. Check all that apply:

The presence of free product or hydrocarbon sheen Surface Water

The presence of free product or hydrocarbon sheen on Groundwater

The presence of contaminated soil in contact with Groundwater

The presence of contaminated soil in contact with Surface water

Yes	Rule 912.b.(1).G: A suspected or actual Spill or Release of any volume where the volume cannot be immediately determined, including a spill or release of any volume that daylight from the subsurface.
No	Rule 912.b.(1).H: Spill or Release resulting in vaporized hydrocarbon mists that leave the Oil and Gas Location or Off-Location Flowline right of way from an Oil and Gas Location and impacts or threatens to impact off-location property. <input type="checkbox"/> Areas offsite of Oil & Gas Location <input type="checkbox"/> Off-Location Flowline right of way
No	Rule 912.b.(1).I: A Release of natural gas that results in an accumulation of soil gas or gas seeps.
No	Rule 912.b.(1).J: A Release that results in natural gas in Groundwater.

SPILL/RELEASE DETAIL REPORTS

#1	Supplemental Report Date: <u>09/28/2025</u>		
FLUIDS	BBL's SPILLED	BBL's RECOVERED	Unknown
OIL	_____	_____	<input checked="" type="checkbox"/>
CONDENSATE	_____	_____	<input checked="" type="checkbox"/>
PRODUCED WATER	_____	_____	<input checked="" type="checkbox"/>
DRILLING FLUID	<u>0</u>	<u>0</u>	<input type="checkbox"/>
FLOW BACK FLUID	<u>0</u>	<u>0</u>	<input type="checkbox"/>
OTHER E&P WASTE	<u>0</u>	<u>0</u>	<input type="checkbox"/>
specify: _____			
Was spill/release completely contained within berms or secondary containment? <u>NO</u> Was an Emergency Pit constructed? <u>NO</u>			
<i>Secondary containment, including walls & floor regardless of construction material, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.</i>			
A Form 15 Pit Report shall be submitted within 30 calendar days after the construction of an emergency pit			
Impacted Media (Check all that apply) <input checked="" type="checkbox"/> Soil <input type="checkbox"/> Groundwater <input type="checkbox"/> Surface Water <input type="checkbox"/> Dry Drainage Feature			
Surface Area Impacted: Length of Impact (feet): _____		Width of Impact (feet): _____	
Depth of Impact (feet BGS): _____		Depth of Impact (inches BGS): _____	
How was extent determined?			
The extent of the release will be determined through a full site assessment and confirmation soil sampling.			
Soil/Geology Description:			
SM-Silty Sand			
Depth to Groundwater (feet BGS) <u>36</u>		Number Water Wells within 1/2 mile radius: <u>4</u>	
If less than 1 mile, distance in feet to nearest	Water Well <u>920</u> None <input type="checkbox"/>	Surface Water <u>1100</u> None <input type="checkbox"/>	
	Wetlands _____ None <input checked="" type="checkbox"/>	Springs _____ None <input checked="" type="checkbox"/>	
	Livestock <u>370</u> None <input type="checkbox"/>	Occupied Building <u>370</u> None <input type="checkbox"/>	
Additional Spill Details Not Provided Above:			
A portion of the location is located within HPH, but the release did not occur within HPH.			

CORRECTIVE ACTIONS

#1 Supplemental Report Date: 09/28/2025

Root Cause of Spill/Release Unknown (Historical)

Other (specify)

Type of Equipment at Point of Spill/Release: Horizontal Separator

If "Other" selected above, specify or describe here:

Empty text box for specifying other equipment details.

Describe Incident & Root Cause (include specific equipment and point of failure)

During facility decommissioning historic impacts were discovered at the separator

Describe measures taken to prevent the problem(s) from reoccurring:

Civitas personnel are coached on safe work practices and conduct routine AVOs while on location

Volume of Soil Excavated (cubic yards):

Disposition of Excavated Soil (attach documentation) [] Offsite Disposal [] Onsite Treatment [] Other (specify)

Volume of Impacted Ground Water Removed (bbls):

Volume of Impacted Surface Water Removed (bbls):

REQUEST FOR CLOSURE

Spill/Release Reports should be closed when impacts have been remediated or when further investigation and corrective actions will take place under an approved Form 27.

- Basis for Closure: [] Corrective Actions Completed (documentation attached, check all that apply)
[] Horizontal and Vertical extents of impacts have been delineated.
[] Documentation of compliance with Table 915-1 is attached.
[] All E&P Waste has been properly treated or disposed.
[X] Work proceeding under an approved Form 27 (Rule 912.c).
Form 27 Remediation Project No: 22792
[] SUSPECTED Spill/Release did not occur or was below Rule 912.a.(5) reporting thresholds.

OPERATOR COMMENTS:

Pursuant to Rule 206.a, Civitas conducted an assessment and identified discrepancies in data previously submitted to the ECMC. Upon further review, two instances were found where exceedances were incorrectly reported as non-exceedances, which led to the project being closed. This document is submitted in compliance with ECMC Rule 911.b. Site investigation and/or remediation activities are currently ongoing at the facility, and Civitas will continue to work with the ECMC to resolve the identified discrepancies.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: Print Name: Luke Kelly
Title: Env. Advisor Date: 09/28/2025 Email: LKelly@civiresources.com

Table with 2 columns: COA Type, Description. Row 1: 0 COA

ATTACHMENT LIST

Att Doc Num **Name**

--	--

Total Attach: 0 Files

General Comments

User Group **Comment**

Comment Date

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
		Stamp Upon Approval

Total: 0 comment(s)