

Inspection Photos

Location Name: PAPPENHEIM-67N64W/24SENW

Location #: 305806



Photo #1

Pappenheim 22-24 (123-23507) Wellsite

Shut-In | SI

CA: Well sign, Emergency # NOT posted

CA: Overgrown vegetation



Photo #2

Pappenheim 12-24, 22-24, 32-24 Battery site

Inactive | Shut-down

Equipment documented: Loc. ID 305808



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: PAPPENHEIM-67N64W/24SENW

Location #: 305806



Photo #3

Pappenheim 12-24, 22-24, 32-24 Battery site

Inactive | Shut-down

Well(s)ite(s), Battery entrance



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources