

Inspection Photos

Location Name: PAPPENHEIM-67N64W/24SWNW

Location #: 305808



Photo #1

Pappenheim 12-24, 22-24, 32-24 Battery site

Inactive | Shut-down

Equipment documented: Loc. ID 305808



Photo #2

Pappenheim 12-24, 22-24, 32-24 Battery site

Inactive | Shut-down

Well(s)ite(s), Battery entrance



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Location Name: PAPPENHEIM-67N64W/24SWNW

Location #: 305808



Photo #3

Pappenheim 12-24, 22-24, 32-24 Battery site

Inactive | Shut-down

Crude oil, produced H2O tank(s): SE corner



Photo #4

Pappenheim 12-24, 22-24, 32-24 Battery site

Inactive | Shut-down

ECD(s), Separator(s)



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: PAPPENHEIM-67N64W/24SWNW

Location #: 305808



Photo #5

Pappenheim 12-24, 22-24, 32-24 Battery site

Inactive | Shut-down

Battery signage



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: PAPPENHEIM-67N64W/24SWNW

Location #: 305808

Associated Well(s)	Location	API	Status
1. Pappenheim 12-24	305808	123-23509	SI
2. Pappenheim 22-24	305806	123-23507	SI
3. Pappenheim 32-24	305807	123-23508	SI

Photo #6

Pappenheim 12-24, 22-24, 32-24 Battery site

Inactive | Shut-down

Associated Well(s)

3: Shut-In | SI



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources