

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
404305470  
Receive Date:  
08/05/2025

Report taken by:  
Nick Cholas

Site Investigation and Remediation Workplan (Supplemental Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by ECMC is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27. This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Closure request is not available for an Initial Site Investigation and Remediation Workplan.

OPERATOR INFORMATION

Name of Operator: <u>NOBLE ENERGY INC</u>	Operator No: <u>100322</u>	<b>Phone Numbers</b>
Address: <u>1099 18TH STREET SUITE 1500</u>		Phone: <u>(970) 730-7281</u>
City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>		Mobile: <u>( )</u>
Contact Person: <u>Dan Peterson</u>	Email: <u>danpeterson@chevron.com</u>	

PROJECT, PURPOSE & SITE INFORMATION

PROJECT INFORMATION

Remediation Project #: 32273 Initial Form 27 Document #: 403573418

PURPOSE INFORMATION

- Rule 913.c.(1): Pit or Cuttings Trench closure.
- Rule 913.c.(2): Buried or partially buried vessel closure, which will be by removal.
- Rule 913.c.(3): Remediation of Spill and Releases pursuant to Rule 912.
- Rule 913.c.(4): Land treatment of Oily Waste pursuant to Rule 905.e.
- Rule 913.c.(5): Closure of Centralized E&P Waste Management Facilities pursuant to Rule 907.h.
- Rule 913.c.(6): Remediation of impacted Groundwater pursuant to Rule 915.e.(3).D, and the contaminant concentrations in Table 915-1.
- Rule 913.c.(7): Investigation and remediation of natural gas in soil or Groundwater.
- Rule 913.c.(8): When requested by the Director due to any potential risk to soil, Groundwater, or surface water.
- Rule 913.c.(9): Decommissioning of Oil and Gas Facilities.
- Rule 913.g: Changes of Operator.
- Rule 915.b: Request to leave elevated inorganics in situ.
- Other: \_\_\_\_\_

SITE INFORMATION

Yes  Multiple Facilities

Facility Type: <u>LOCATION</u>	Facility ID: <u>311342</u>	API #: _____	County Name: <u>WELD</u>
Facility Name: <u>UPRR 36 PAN AM C-64N65W 33SWSW</u>	Latitude: <u>40.263230</u>	Longitude: <u>-104.675600</u>	
** correct Lat/Long if needed: Latitude: <u>40.261879</u>		Longitude: <u>-104.675637</u>	
QtrQtr: <u>SWSW</u>	Sec: <u>33</u>	Twp: <u>4N</u>	Range: <u>65W</u> Meridian: <u>6</u> Sensitive Area? <u>Yes</u>

Facility Type: <u>SPILL OR RELEASE</u>	Facility ID: <u>489199</u>	API #: _____	County Name: <u>WELD</u>
Facility Name: <u>UPRR 36 Pan Am C-64N65W 33SWSW</u>	Latitude: <u>40.261862</u>	Longitude: <u>-104.675624</u>	
** correct Lat/Long if needed: Latitude: _____		Longitude: _____	
QtrQtr: <u>SWSW</u>	Sec: <u>33</u>	Twp: <u>4N</u>	Range: <u>65W</u> Meridian: <u>6</u> Sensitive Area? <u>Yes</u>

**SITE CONDITIONS**

General soil type - USCS Classifications SW \_\_\_\_\_

Most Sensitive Adjacent Land Use Cropland \_\_\_\_\_

Is domestic water well within 1/4 mile? Yes \_\_\_\_\_

Is surface water within 1/4 mile? No \_\_\_\_\_

Is groundwater less than 20 feet below ground surface? No \_\_\_\_\_

**Other Potential Receptors within 1/4 mile**

Farming Structure 0.13/0.14/0.14 NE  
Residential Structure 0.11 NE

# SITE INVESTIGATION PLAN

## TYPE OF WASTE:

- |                                                    |                                                      |                                        |
|----------------------------------------------------|------------------------------------------------------|----------------------------------------|
| <input checked="" type="checkbox"/> E&P Waste      | <input type="checkbox"/> Other E&P Waste             | <input type="checkbox"/> Non-E&P Waste |
| <input checked="" type="checkbox"/> Produced Water | <input type="checkbox"/> Workover Fluids             | _____                                  |
| <input checked="" type="checkbox"/> Oil            | <input type="checkbox"/> Tank Bottoms                |                                        |
| <input checked="" type="checkbox"/> Condensate     | <input type="checkbox"/> Pigging Waste               |                                        |
| <input type="checkbox"/> Drilling Fluids           | <input type="checkbox"/> Rig Wash                    |                                        |
| <input type="checkbox"/> Drill Cuttings            | <input type="checkbox"/> Spent Filters               |                                        |
|                                                    | <input type="checkbox"/> Pit Bottoms                 |                                        |
|                                                    | <input type="checkbox"/> Other (as described by EPA) | _____                                  |

## DESCRIPTION OF IMPACT

Impacted?	Impacted Media	Extent of Impact	How Determined
UNDETERMINED	GROUNDWATER	NA	Lab Analysis or Field Screening, if encountered
Yes	SOILS	Refer to ECMC Document # 404077331	Lab Analysis and Field Screening

## INITIAL ACTION SUMMARY

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

A site investigation was conducted pursuant to ECMC Rule 911 at the UPRR PAN AM T4N-R65W-S33 L01 Facility and Tank Battery location.

On 12/06/24, 12/09/24, and 12/10/24, the tank battery was decommissioned in accordance with ECMC rules. Laboratory soil samples were collected from the partially-buried produced water vessel excavation (PWV01-B@4') and field screening samples were taken from the N, E, S, & W sidewalls (PWV01-N, E, S, W). The screening sample with the highest PID (PWV01-S@3') was collected for laboratory analysis from the S sidewall. Lab samples were also collected beneath the above ground storage tank (AST01@0-6") and beneath the the separator riser of the dumpline (SEP01-DL@3') and the flowline (SEP01-FL@3'). Additionally, field screening samples were collected beneath the meter house (MH01@0-6").

## PROPOSED SAMPLING PLAN

### Proposed Soil Sampling

Will soil samples be collected as part of this investigation? ( Number, type (grab/composite), analyses, and locations of samples ):

Soils were collected as described in the Initial Action Summary of this Supplemental Form 27. Soil samples were analyzed by a certified laboratory for the full extent of Table 915-1, including but not limited to: TPH (total volatile [C6-C10] and extractable [C10-C36] hydrocarbons) organic compounds in soil per ECMC Table 915-1, and EC, SAR, pH, metals, and boron. All samples collected were analyzed by a certified laboratory using approved ECMC laboratory analysis methods.

### Proposed Groundwater Sampling

Will groundwater samples be collected as part of this investigation? ( Number, analyses, and locations of samples ):

If groundwater is encountered during the site investigation a grab groundwater sample will be collected and analyzed for all organic compounds and inorganic parameters per ECMC Table 915-1.

### Proposed Surface Water Sampling

Will surface water samples be collected as part of this investigation? ( Number, analyses, and locations of samples ):

## Additional Investigative Actions

Additional alternative investigative actions described in attached Site Investigation Plan ( summary ):

Visual inspection at the tank battery area occurred during decommissioning activities. Field personnel field screened all disturbed areas using visual and olfactory senses to determine if laboratory confirmation sampling was required. A detailed summary of decommissioning activities, including field notes, site photos, figures, and laboratory analytical results, is attached to a previous Form 27 (ECMC Document #404191535).

# SITE INVESTIGATION REPORT

## SAMPLE SUMMARY

**Soil**

Number of soil samples collected 5  
Number of soil samples exceeding 915-1 5  
Was the areal and vertical extent of soil contamination delineated? No  
Approximate areal extent (square feet) 500

**NA / ND**

ND Highest concentration of TPH (mg/kg) \_\_\_\_\_  
-- Highest concentration of SAR 1.53  
BTEX > 915-1 No  
Vertical Extent > 915-1 (in feet) 4

**Groundwater**

Number of groundwater samples collected 0  
Was extent of groundwater contaminated delineated? Yes  
Depth to groundwater (below ground surface, in feet) \_\_\_\_\_  
Number of groundwater monitoring wells installed \_\_\_\_\_  
Number of groundwater samples exceeding 915-1 \_\_\_\_\_

Highest concentration of Benzene (µg/l) \_\_\_\_\_  
Highest concentration of Toluene (µg/l) \_\_\_\_\_  
Highest concentration of Ethylbenzene (µg/l) \_\_\_\_\_  
Highest concentration of Xylene (µg/l) \_\_\_\_\_  
Highest concentration of Methane (mg/l) \_\_\_\_\_

**Surface Water**

0 Number of surface water samples collected  
\_\_\_\_\_ Number of surface water samples exceeding 915-1  
If surface water is impacted, other agency notification may be required.

**OTHER INVESTIGATION INFORMATION**

Were impacts to adjacent property or offsite impacts identified?

\_\_\_\_\_

Were background samples collected as part of this site investigation?

\_\_\_\_\_

Was investigation derived waste (IDW) generated as part of this investigation?

Volume of solid waste (cubic yards) \_\_\_\_\_ Volume of liquid waste (barrels) \_\_\_\_\_

Is further site investigation required?

Concurrently with the remedial excavation that is proposed in the Remedial Action Plan section of this Form 27, a supplemental site investigation (SSI) will be completed to collect background soil samples to determine if elevated pH and arsenic concentrations are attributed to native soil conditions at the site. During site investigation activities, a soil sample will be field screened by use of a photoionization detector (PID) at the location indicated on the approved initial proposed site investigation map (IF27 #403573418) south of the AST. Proposed background soil sample and grab sample locations are shown on the proposed soil boring locations map attached to a previous Form 27 (ECMC Document # 404077331). The SSI will be completed in accordance with the proposed implementation schedule, and the results of the SSI will be submitted on a subsequent Form 27.

**REMEDIAL ACTION PLAN**

Does this Supplemental Form 27A include changes to a previously approved Remedial Action Plan? Yes

**SOURCE REMOVAL SUMMARY**

Describe how source is to be removed.

The benzo(a)anthracene exceedances observed at soil sample locations SEP01-FL@3' and SEP01-DL@3' will be removed through a remedial excavation. Remedial excavation confirmation soil samples will be collected and analyzed for full ECMC Table 915-1 constituents.

**REMEDIATION SUMMARY**

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

Remedial excavation confirmation soil samples will be collected and analyzed for full ECMC Table 915-1 constituents. The results of the remedial excavation will be submitted on a subsequent Form 27.

**Soil Remediation Summary**

In Situ

Ex Situ

\_\_\_\_\_ Bioremediation ( or enhanced bioremediation )

\_\_\_\_\_ Excavate and offsite disposal

Chemical oxidation  
 Air sparge / Soil vapor extraction  
 Natural Attenuation  
 Other \_\_\_\_\_

If Yes: Estimated Volume (Cubic Yards) \_\_\_\_\_  
Name of Licensed Disposal Facility or ECMC Facility ID # \_\_\_\_\_  
 Excavate and onsite remediation  
 Land Treatment  
 Bioremediation (or enhanced bioremediation)  
 Chemical oxidation  
 Other \_\_\_\_\_

**Groundwater Remediation Summary**

Bioremediation ( or enhanced bioremediation )  
 Chemical oxidation  
 Air sparge / Soil vapor extraction  
 Natural Attenuation  
 Other \_\_\_\_\_

**GROUNDWATER MONITORING**

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

Groundwater was not encountered during initial decommissioning activities.

# REMEDIATION PROGRESS UPDATE

## PERIODIC REPORTING

### Approved Reporting Schedule:

Quarterly    Semi-Annually    Annually    Other

### Request Alternative Reporting Schedule:

Semi-Annually    Annually    Other

Rule 913.e:

After initial approval of a Form 27, the Operator will provide quarterly update reports in a Supplemental Form 27 to document progress of site investigation and remediation, unless an alternative reporting schedule has been requested by the Operator and approved by the Director. The Director may request a more frequent reporting schedule based on site-specific conditions.

**Report Type:**    Groundwater Monitoring    Land Treatment Progress Report    O&M Report  
 Other Timeline Update

## Adequacy of Operator's General Liability Insurance and Financial Assurance

Describe the adequacy of the Operator's general liability insurance and Financial Assurance to fully address the anticipated costs of Remediation, including the estimated remaining cost for this project (below).

If this information has been provided on a Form 27 within the last 12 months, provide the Document Number of that form.

Noble intends to directly address the costs of remediation at the locations as part of our asset retirement obligation process and operations. Noble has general liability insurance (policies MWZZ316714 and MWZX316724) and financial assurance in compliance with ECMC rules. Records are available on the ECMC's website. The cost for remediation is an estimate only, costs may change upwards or downward based on site-specific information. Noble makes no representation or guarantees as to the accuracy of the estimate.

Operator anticipates the remaining cost for this project to be: \$ 50000

## WASTE DISPOSAL INFORMATION

Was E&P waste generated as part of this remediation? No

Describe beneficial use, if any, of E&P Waste derived from this remediation project:

Volume of E&P Waste (solid) in cubic yards \_\_\_\_\_

E&P waste (solid) description \_\_\_\_\_

ECMC Disposal Facility ID #, if applicable: \_\_\_\_\_

Non-ECMC Disposal Facility: \_\_\_\_\_

Volume of E&P Waste (liquid) in barrels \_\_\_\_\_

E&P waste (liquid) description \_\_\_\_\_

ECMC Disposal Facility ID #, if applicable: \_\_\_\_\_

Non-ECMC Disposal Facility: \_\_\_\_\_

# REMEDIATION COMPLETION REPORT

## REMEDIATION COMPLETION SUMMARY

Is this a Final Closure Request for this Remediation Project? No

If YES:

Compliant with Rule 913.h.(1).

Compliant with Rule 913.h.(2).

Compliant with Rule 913.h.(3).

Do all soils meet Table 915-1 standards? \_\_\_\_\_

Does the previous reply indicate consideration of background concentrations? \_\_\_\_\_

Does Groundwater meet Table 915-1 standards? \_\_\_\_\_

Is additional groundwater monitoring to be conducted? \_\_\_\_\_

Operator shall comply with the ECMC 1000-Series Reclamation Requirements for all impacted and disturbed areas.

## RECLAMATION PLAN

### RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

Reclamation will be in accordance with ECMC 1000 Series Rules.

Is the described reclamation complete? Yes \_\_\_\_\_

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

Interim  Final

Did the Surface Owner provide the seed mix? \_\_\_\_\_

If YES, does the seed mix comply with local soil conservation district recommendations? \_\_\_\_\_

Did the local soil conservation district provide the seed mix? \_\_\_\_\_

### SITE RECLAMATION DATES

Proposed date of commencement of Reclamation. 12/06/2024

Proposed date of completion of Reclamation. 08/05/2027

## IMPLEMENTATION SCHEDULE

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

### PRIOR DATES

Date of Surface Owner notification/consultation, if required. 10/26/2023

Actual Spill or Release date, or date of discovery. 01/31/2025

### SITE INVESTIGATION DATES

Date of Initial Actions described in Site Investigation Plan (start date). 12/06/2024

Proposed site investigation commencement. 02/20/2026

Proposed completion of site investigation. 02/20/2026

### REMEDIAL ACTION DATES

Proposed start date of Remediation. 08/05/2025

Proposed date of completion of Remediation. 04/05/2026

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

Change from approved implementation schedule per Rule 913.d.(2).

Basis for change in implementation schedule:

The implementation schedule has been changed due to the decommissioning of the UPRR PAN AM C-64N65W 33SWSW tank battery and necessity for remedial excavation and SSI activities adjacent to the tank battery. The SSI is currently scheduled for completion on 02/20/2026.

**OPERATOR COMMENT**

This Form 27 is being submitted to maintain quarterly reporting compliance during the third quarter of 2025 for completion of remedial excavation and supplemental site investigation (SSI) activities at the UPRR 36 PAN AM C-64N65W 33SWSW Tank Battery location (REM # 32273).

The remedial excavation and SSI will be completed in accordance with the workplan proposed in the previous Form 27 (ECMC Document # 404077331). The SSI is currently scheduled for 02/20/2026.

Pursuant to Rule 913.e, quarterly reporting will be conducted until closure criteria are achieved for the remediation project. The results of the SSI and remedial excavation will be submitted on a subsequent Form 27.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: Michael Liston \_\_\_\_\_

Title: Environmental Consultant \_\_\_\_\_

Submit Date: 08/05/2025 \_\_\_\_\_

Email: mliston@tasman-geo.com \_\_\_\_\_

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with ECMC Rules and applicable orders and is hereby approved.

ECMC Approved: Nick Cholas \_\_\_\_\_

Date: 09/29/2025 \_\_\_\_\_

Remediation Project Number: 32273 \_\_\_\_\_

**COA Type****Description**

	ECMC has processed this form as an update; no analytical was attached thus approval of this form does not imply any agreement with comments on completion of site investigation. All ongoing/unaddressed comments/COAs from previous Forms remain applicable.
--	---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

1 COA

**ATTACHMENT LIST**

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

**Att Doc Num****Name**

404305470	INVESTIGATION/REMEDATION WORKPLAN (SUPPLEMENTAL)
404372656	FORM 27-SUPPLEMENTAL-SUBMITTED

Total Attach: 2 Files

**General Comments****User Group****Comment****Comment Date**

Environmental	Operator states: "The SSI is currently scheduled for 02/20/2026."	09/29/2025
---------------	-------------------------------------------------------------------	------------

Total: 1 comment(s)