Inspection Photos

09/25/2025

Operator: EAGLE OPERATING INC #26155

Location ID: 316345

Inspection Doc: 718100888

Rio Blanco County, CO

Aaron Trujillo
Western Reclamation Work Lead
ECMC

Inspection Photos
Operator Name: EAGLE OPERATING INC #26155
Location ID: 316345

Photo 1: Photos 1-2 taken from the northeast end of the Location. Photos provide an overview from southeast, south, west to northwest. Pursuant to Resolution #404363872 weeds were removed and disposed of properly, and Location reseeded. Weeds have not been removed/disposed as indicated by the FIRR. Unable to find evidence of additional reclamation work.

Inspection Photos
Operator Name: EAGLE OPERATING INC #26155
Location ID: 316345

Photo 2: See comments under photo 1.

Inspection Photos
Operator Name: EAGLE OPERATING INC #26155
Location ID: 316345

Photo 3: Photo shows the surface of the Location. Photo example showing Noxious weeds (Halogeton) remain established on the Location, and have not been removed or disposed; plants have reached viable maturity and are flowering. Additional seeding efforts also not apparent; drill rows associated with drill seeding not observed; no seed observed on the soil surface if broadcast seeding was performed.