

Inspection Photos

09/25/2025

Operator: EAGLE OPERATING INC #26155

Location ID: 397838

Inspection Doc: 718100890

Rio Blanco County, CO

Aaron Trujillo

Western Reclamation Work Lead

ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: EAGLE OPERATING INC #26155

Location ID: 397838



Photo 1: Photos taken from the north end of the Location. Photos provide an overview from southeast southwest. Pursuant to Resolution #404363838 weeds were removed and disposed of properly, and Location reseeded. Weeds have not been removed/disposed as indicated by the FIRR. Unable to find evidence of additional reclamation work.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: EAGLE OPERATING INC #26155

Location ID: 397838



Photo 2: Photo taken from the north end of the Location, facing south.
See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: EAGLE OPERATING INC #26155

Location ID: 397838



Photo 3: Photo taken from the south end of the Location, facing north. See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: EAGLE OPERATING INC #26155

Location ID: 397838



Photo 4: Photo shows the surface of the Location. Photo example showing Noxious weeds (Halogeton) remain established on the Location, and have not been removed or disposed; plants have reached viable maturity and are flowering. Additional seeding efforts also not apparent; drill rows associated with drill seeding not observed; no seed observed on the soil surface if broadcast seeding was performed.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources