



Inspection Photos  
Location Name: ZARLENGO 14-4  
Location ID: 320458



Photo#1 Pumpjack/CA:Weeds unmanaged

Photo#2 Production Equipment/CA:Weeds unmanaged

Inspection Photos  
Location Name: ZARLENGO 14-4  
Location ID: 320458



Photo#3 Backside of production tank/**CA:Weeds unmanaged**

Photo#4 Production Tank/**CA:Weeds unmanaged**