

Inspection Photos
Location Name: Grant #3
API #:05-123-09307



Photo 1: Wellhead sign

Photo 2: Pumpjack

Inspection Photos
Location Name: Grant #3
API #:05-123-09307



Photo 3: Overgrown vegetation



Photo 4: Overgrown vegetation

Inspection Photos
Location Name: Grant #3
API #:05-123-09307



Photo 5: overgrown vegetation

Photo 6: overgrown vegetation