

Inspection Photos
Location Name: NGL C8A
Location ID: 421249



Photo 1 – Well Sign

Photo 2 – Wellhead

Inspection Photos
Location Name: NGL C8A
Location ID: 421249




Photo 3 – Tubing Gauge

Photo 4 – Casing Gauge

Inspection Photos
Location Name: NGL C8A
Location ID: 421249



Photo 5 – Bradenhead Gauge