

Inspection Photos

Location Name: KOHLHOFF USX AB/21-06P

Location #: 413553



Photo #1

Kohlhoff USX AB 21-06P (123-30551) Wellsite

Plugged & Abandoned | PA

Cut / Capped

~ 10 yds.



Photo #2

Kohlhoff USX AB 21-07P, 21-06P Battery site

Abandoned: ALL Equipment Removed

Formerly served: 2: Wellsite(s);

Plugged & Abandoned | PA

prior photo



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources