

Inspection Photos

Location Name: FAULK USX AB-67N64W/21SESE

Location #: 410100



Photo #1

Faulk USX AB 21-16P (123-30148) Wellsite

Plugged & Abandoned | PA

Cut / Capped

~ 10 yds.



Photo #2

Mojack USX AB21-15, Faulk USX AB 21-10P,

Faulk USX AB 21-16P Battery site

Abandoned: ALL Equipment Removed

Formerly served: 3: Wellsite(s);

Plugged & Abandoned | PA



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources