

Inspection Photos

Location Name: LETTERLY-USX AB-67N64W/23SWSW

Location #: 310465



Photo #1

Letterly-USX AB 23-13 (123-26439) Wellsite

Temporarily Abandoned | TA

CA: Overgrown vegetation

prior photo



Photo #2

Letterly-USX AB 23-13 Wellsite

Temporarily Abandoned | TA

Overgrown vegetation: Mitigated

Date: 09/29/2025

Operator provided photo



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources