

Inspection Photos

Location Name: PAPPENHEIM USX AB-67N64W/13SWSW

Location #: 310329



Photo #1

Pappenheim USX AB 13-13 (123-26250) Wellsite

Shut-In | SI

CA: Invalid Emergency Number

prior photo



Photo #2

Pappenheim USX AB 13-13 Wellsite

Temporarily Abandoned | TA

Valid Emergency Number: Posted

Date: 09/30/2025

Operator provided photo



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources