

Inspection Photos  
Location Name: BOXELDER #22-28  
Location ID: 320454



Photo #1 Tanks & weeds.

Photo #2 thief hatch open.

Inspection Photos  
Location Name: BOXELDER #22-28  
Location ID: 320454



Photo #3 stained soil



Photo #4 Weeds, separator & ECD.

Inspection Photos  
Location Name: BOXELDER #22-28  
Location ID: 320454



Photo #5 Stained soil & well head.



Photo #6 Well head & stained soil.