

Work Completion Report

Contractor: H2 Enterprises (H2)

JOB DETAILS

Job Name	Month/Season	Completed By	Completion Date
MILLER X 31-03 (2025 Seasonal)	Fall	Dusty Hayden	9/19/2025

Work Summary	Reclamation Type	Land Use
Mowed and drilled 1 acre on tb access road and well head	Final Maint	Pasture

One-Call Number	Red Zone Rep	Red Zone Date

WORK TASK

Task Name	Priority	COGCC Compliance	Task Location and Notes/Instructions
Final Reclamation Maintenance		No	Location(s): MILLER X 31-03 Notes: May include innerseeding, mowing, spraying, debris clean-up. If locates and red zone are required, please notify Oxy to modify job assignment and schedule on-site meeting. If the location does not need work completed, please complete a work completion report. If location is ready for Form 4, please complete inspection and add Form 4 work task

COMPLETION DETAILS

Total Area Affected: **43,560 sq ft**
 Seed Mix: **Dryland Pasture (15.00 lbs)**
 Crop Type:
 Soil Type: **Sandy Loam**
 Stabilization Date:
 Seeding Date: **9/19/2025**
 Mulch: **None**
 Straw Bales: **NA**
 Soil Amendment Type: **None**
 Soil Amendment Rate: **NA**
 Imported Top Soil: **NA**
 Top Soil Source: **NA**
 General Notes: **Oxrm1391**

Photo Name: Pre-Completion

Description:



Photo Name: Post-Completion

Description:



Photo Name: A

Description:



Photo Name: B

Description:



Photo Name: C

Description:



Photo Name: D

Description:



Photo Name: E

Description:

