0:00
58.00

Schneider Summit Services
PO Box 983038
Park City, UT 84098

DAILY OPERATIONS REPORT

Date (1st Hour):	08/31/25	**Operator**	**Bison IV Operating**	**Well Name:**	**Graham 1**		API # 05-123-05365
Field:	Baja			**Consultant:**	Rusty Tucker / Colt Kenney	**AFE #:**	8306..235
County:	Weld			**Phone:**	970-380-2326 / 970-712-0525	**Csg Depth / TD:**	SC @416'
Operation:	Re-entry P&A			**Rig Contractor:**	Hurricane #9	**Size / Grade:**	
				Location:	NESW Sec 13, T7N, R60W	**Weight / Thread:**	
				Lat/Long:	40.573356 / -104.043390	**Perforations:**	

BREAKDOWN OF OPERATIONS

From	To	Hrs	Description
18:00	22:30	4:30	MIRU Hurricane rig and support equipment, N/U KLX 9" BOPE, Rig up rig floor
22:30	23:30	1:00	R/U power swivel and pipe wrangler.
23:30	4:00	4:30	M/U RIH with 7 7/8" tri cone, Tag cement @ 44'. Start drilling sand/cement. Drill out to 93' and fall through. Wash through heavy/thick mud RIH tag @364' pressure test 250 psi good test.
4:00	6:00	2:00	Continue to drill to 490', circulate clean
6:00			

TUBING, BHA, Rods

Quantity	OD	ID	Description	Length	Top

End of Tubing:

0:00
58.00

Schneider Summit Services
PO Box 983038
Park City, UT 84098

DAILY OPERATIONS REPORT

Date (1st Hour):	09/01/25	**Operator**	**Bison IV Operating**	**Well Name:**	**Graham 1**		API # 05-123-05365
Field:	Baja			**Consultant:**	Rusty Tucker / Colt Kenney	**AFE #:**	8306..235
County:	Weld			**Phone:**	970-380-2326 / 970-712-0525	**Csg Depth / TD:**	SC @416'
Operation:	Re-entry P&A			**Rig Contractor:**	Hurricane #9	**Size / Grade:**	
				Location:	NESW Sec 13, T7N, R60W	**Weight / Thread:**	
				Lat/Long:	40.573356 / -104.043390	**Perforations:**	

BREAKDOWN OF OPERATIONS

From	To	Hrs	Description
6:00	9:00	3:00	Hang back the swivel & TOOH, RIH w/muleshoe & circulate down to 656'
9:00	12:00	3:00	Started getting thick mud and big chunks of dehydrated mud that was plugging our flowlines, had to keep unplugging them, circulated down to 785'.
12:00	15:00	3:00	Still getting heavy thick mud continue to 948'
15:00	18:00	3:00	Circulate down to 1,306'. Rack back swivel, R/U back up pump.
18:00	21:00	3:00	Circulate down to 2,187'
21:00	0:00	3:00	Circulate down to 3,002'
0:00	3:00	3:00	Pluging up on flow line at the shaker tank work on cleaning out lines. Circulate down to 3,654'
3:00	6:00	3:00	Circulate down to 4,235'
6:00			

TUBING, BHA, Rods

Quantity	OD	ID	Description	Length	Top
				End of Tubing:	

0:00
58.00

Schneider Summit Services
PO Box 983038
Park City, UT 84098

DAILY OPERATIONS REPORT

Date (1st Hour):	09/02/25	**Operator**	**Bison IV Operating**	**Well Name:**	**Graham 1**		API # 05-123-05365
Field:	Baja			**Consultant:**	Rusty Tucker / Colt Kenney	**AFE #:**	8306..235
County:	Weld			**Phone:**	970-380-2326 / 970-712-0525	**Csg Depth / TD:**	SC @416'
Operation:	Re-entry P&A			**Rig Contractor:**	Hurricane #9	**Size / Grade:**	
				Location:	NESW Sec 13, T7N, R60W	**Weight / Thread:**	
				Lat/Long:	40.573356 / -104.043390	**Perforations:**	

BREAKDOWN OF OPERATIONS

From	To	Hrs	Description
6:00	9:00	3:00	Circulate from 4,235' to 5,215'
9:00	12:00	3:00	Circulate to 5,542'
12:00	15:00	3:00	Circulate down to 6,065 & circulate clean. RU Axis Cementers & held JSA. Axis pumped 100 sks of 15.8#, 1.15 Y w/retarder & displaced w/33.1 BBLS, good returns throughout
15:00	16:45	1:45	LD 138 JTS, EOT @ 1,560'
16:45	18:00	1:15	Est circ with rig pump and mud circ clean wait for crew change. Confirm static conditions. No pressure or of fluid migration,
18:00	18:15	0:15	Pump 75 sks of 15.8#, 1.15 Y w/2% CC & displaced w/7.4 BBLS, good returns throughout
18:15	18:45	0:30	Lay down 10 joints stand back 19 stands.
18:45	22:45	4:00	WOC 4 hour.
22:45	0:20	1:35	RIH with mule shoe and tubing tag cement @1,326'. Lay down tubing
0:20	0:40	0:20	Pump 215 sks of 15.8#, 1.15 Y w/2% CC, good returns throughout, cement back to surface.
0:40	4:00	3:20	Lay down all tubing, R/D rig floor N/D BOPE, top of well with 20 sks of 15.8#, 1.15 Y
4:00	6:00	2:00	Clean tanks RDMO.
6:00			

TUBING, BHA, Rods

Quantity	OD	ID	Description	Length	Top
				End of Tubing:	

Schneider Summit Services

0:00
58.00

Schneider Summit Services
PO Box 983038
Park City, UT 84098

DAILY OPERATIONS REPORT

Date (1st Hour):	09/12/25	**Operator**	**Bison IV Operating**	**Well Name:**	**Graham 1**		API # 05-123-05365
Field:	Baja			**Consultant:**	Rusty Tucker / Colt Kenney	**AFE #:**	8306..235
County:	Weld			**Phone:**	970-380-2326 / 970-712-0525	**Csg Depth / TD:**	SC @416'
Operation:	Re-entry P&A			**Rig Contractor:**	Hurricane #9	**Size / Grade:**	
				Location:	NESW Sec 13, T7N, R60W	**Weight / Thread:**	
				Lat/Long:	40.573356 / -104.043390	**Perforations:**	

BREAKDOWN OF OPERATIONS

From	To	Hrs	Description
6:00			SAFETY MEETING /JASA
			ROAD ROUSTABOUT CREW AND BACK HOE TO LOCATION.
			DUG UP CASING AND CUT OFF 5' BELOW GROUND LEVEL.
			CONDUCTED 15 MINUTE BUBBLE TEST AND NO BUBBLES WERE SEEN.
			WELDED PLATE ON SURFACE CASING.
			BACKFILL AND CLEAN UP LOCATION.
			ROAD TO NEXT LOCATION.

TUBING, BHA, Rods

Quantity	OD	ID	Description	Length	Top
				End of Tubing:	