

Inspection Photos

09/24/2025

Operator: TEP Rocky Mountain LLC #96850

Location ID: 413683

Inspection Doc: 719200278

Garfield County, CO

Emily Gaasche
NW Reclamation Specialist
ECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 413683



Photo 1: Photos showing an overview of the location looking northeast and south, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 413683



Photo 2: Photos showing an overview of the location looking east and west, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 413683



Photo 3: Photos showing straw wattles throughout the location are in disrepair. Maintain or implement stormwater BMPs.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 413683



Photo 4: Photos showing erosion and sediment transportation at the XX portion of the location. Stormwater controls appear to be missing or insufficient; comply with 1002.f. and implement or maintain stormwater BMPs.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 413683



Photo 5: Photos showing sediment is overtopping wattles near and around production equipment. Stormwater BMPs are missing or insufficient. Comply with 1002.f.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 413683



Photo 6: Photos showing an overview of the southern interim areas. Interim areas are composed of smooth brome with trace amounts of big sagebrush. Interim areas are progressing towards 1003 reclamation requirements.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources