

Inspection Photos

10/8/2025

Operator: QB ENERGY OPERATING LLC

#10844

Location ID: 416051

Inspection Doc: 718100894

Garfield County, CO

Aaron Trujillo

Western Reclamation Work Lead

ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 416051



Photo 1: Photos taken from the central areas of the Location, facing south. Photos provide an overview of the Location. Photos also show that compaction alleviation has not been performed in accordance with Rules 1004.a and 1003.c (cross-ripping to a depth of 18 inches). Operator has only ripped in one direction. A compaction test was performed between the furrows of where the rippers traveled, and a zone of compaction was observed at a depth of ~4-6 inches.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 416051



Photo 2: Continued from photo 1. Photo shows compaction at ~4-6 inches subsurface, between the furrows of where the rippers traveled. Location has not been cross-ripped in accordance with Rules 1004.a and 1003.c



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 416051



Photo 3: Photos taken from the north and northwest end of the Location. Photos examples showing noxious weed observed establishing.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources