

# Inspection Photos

10/8/2025

**Operator:** QB ENERGY OPERATING LLC

#10844

**Location ID:** 335594

**Inspection Doc:** 718100896

Garfield County, CO

Aaron Trujillo

Western Reclamation Work Lead

ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 335594



**Photo 1:** Photos taken from the south end of the Location. Photos provide an overview from west, northwest, northeast to east.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 335594



**Photo 2:** See comments under photo 1.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 335594



**Photo 3:** Photos taken from the wells. Signage pursuant to Rule 605.d has not been posted at the wellheads.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 335594



**Photo 4:** Photos taken from the northwest end of the Location, facing north and northwest respectively. BMPs to minimize erosion, degradation and to stabilize the slopes are missing or insufficient.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 335594



**Photo 5:** Photos examples showing halogeton establishment (brown colored vegetation within photos) on the working pad surface.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources