

# Inspection Photos

10/8/2025

**Operator:** QB ENERGY OPERATING LLC

#10844

**Location ID:** 487650

**Inspection Doc:** 718100900

Rio Blanco County, CO

Aaron Trujillo

Western Reclamation Work Lead

ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 487650



**Photo 1:** Photos 1-2 taken from the northeast end of the working pad surface. Photos provide an overview from southeast, south, west to northwest.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 487650



**Photo 2:** See comments under photo 1.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 487650



**Photo 3:** Photos taken from the location entrances on the south and west ends of the Location. Photos show a VTC per good engineering practices have not been installed. Operator has placed smooth and small gravel material at the entrances, rather than coarse aggregate. “Tracking Pad” as installed is inadequate.



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

## Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 487650



**Photo 4:** Photos shows signage placed at location entrance.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources