

Inspection Photos

10/7/2025

Operator: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 311663

Inspection Doc: 718100902

Garfield County, CO

Aaron Trujillo

Western Reclamation Work Lead

ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 311663



Photo 1: Photos taken from the interim areas on the north end of the Location, facing southeast and south. Photos provide an overview of the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 311663



Photo 2: Photos taken from the stormwater diversion ditch within the north end of the Location. BMPs (Rip-rap, check dams) have filled with sediment and/or are no longer in proper functioning condition.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 311663



Photo 3: See comments under photo 2.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 311663



Photo 4: BMPs to stabilize the working pad surface, as well as to minimize vehicle erosion, degradation and sediment transport show sign of disrepair. Maintenance advised.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources