

Inspection Photos

10/7/2025

Operator: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335636

Inspection Doc: 718100904

Garfield County, CO

Aaron Trujillo

Western Reclamation Work Lead

ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335636



Photo 1: Photo shows work over rig on Location at time of inspection.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335636



Photo 2: Photos taken from the edge of the working pad surface on the east end of the Location, facing north. Additional reclamation efforts apparent. Unable to find evidence that BMPs to manage runoff from the working pad surface have been installed.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335636



Photo 3: Photo taken from the west end of the Location. Photo shows what appears to be cement waste has been improperly stored on the Location near the stormwater diversion ditch. Materials observed spilling beyond the liner.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335636



Photo 4: Photos taken from the west end of the Location. Photos show trash debris improperly stored on the Location, rather than an appropriate receptacle.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources



Photo 5: What appears to be oily waste observed spilled around areas of the trailer on the west end of the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources