

# Inspection Photos

10/7/2025

**Operator:** TEP ROCKY MOUNTAIN LLC #96850

**Location ID:** 335742

**Inspection Doc:** 718100906

Garfield County, CO

Aaron Trujillo

Western Reclamation Work Lead

ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335742



**Photo 1:** Photos 1-2 taken from the southeast end of the Location. Photos show interim reclamation has been performed within the southern areas of the Location. This CA has been resolved.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335742



**Photo 2:** See comments under photo 1.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335742



**Photo 3:** Open ended pipe riser on next to separator equipment.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335742



**Photo 4:** Live animal trap stored next to separators.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources