

**State of Colorado**  
**Energy & Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
404370492

Receive Date:  
09/26/2025

Report taken by:  
Krystal Heibel

**Site Investigation and Remediation Workplan (Supplemental Form)**

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by ECOM is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27. This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Closure request is not available for an Initial Site Investigation and Remediation Workplan.

**OPERATOR INFORMATION**

Name of Operator: <u>WESTERN OPERATING COMPANY</u>	Operator No: <u>95620</u>	<b>Phone Numbers</b>
Address: <u>1165 DELAWARE STREET #200</u>		Phone: <u>(303) 726-8650</u>
City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80204</u>		Mobile: <u>( )</u>
Contact Person: <u>Steve James</u>	Email: <u>steve@westernoperating.com</u>	

**PROJECT, PURPOSE & SITE INFORMATION**

**PROJECT INFORMATION**

Remediation Project #: 27155 Initial Form 27 Document #: 403273080

**PURPOSE INFORMATION**

- Rule 913.c.(1): Pit or Cuttings Trench closure.
- Rule 913.c.(2): Buried or partially buried vessel closure, which will be by removal.
- Rule 913.c.(3): Remediation of Spill and Releases pursuant to Rule 912.
- Rule 913.c.(4): Land treatment of Oily Waste pursuant to Rule 905.e.
- Rule 913.c.(5): Closure of Centralized E&P Waste Management Facilities pursuant to Rule 907.h.
- Rule 913.c.(6): Remediation of impacted Groundwater pursuant to Rule 915.e.(3).D, and the contaminant concentrations in Table 915-1.
- Rule 913.c.(7): Investigation and remediation of natural gas in soil or Groundwater.
- Rule 913.c.(8): When requested by the Director due to any potential risk to soil, Groundwater, or surface water.
- Rule 913.c.(9): Decommissioning of Oil and Gas Facilities.
- Rule 913.g: Changes of Operator.
- Rule 915.b: Request to leave elevated inorganics in situ.
- Other: \_\_\_\_\_

**SITE INFORMATION**

Yes Multiple Facilities

Facility Type: <u>PIT</u>	Facility ID: <u>100310</u>	API #: _____	County Name: <u>LOGAN</u>
Facility Name: <u>PROPST 1A</u>	Latitude: <u>40.892996</u>	Longitude: <u>-103.264618</u>	
	** correct Lat/Long if needed: Latitude: <u>40.892798</u>	Longitude: <u>-103.264685</u>	
QtrQtr: <u>SWSW</u> Sec: <u>26</u> Twp: <u>11N</u> Range: <u>53W</u> Meridian: <u>6</u> Sensitive Area? <u>Yes</u>			

Facility Type: <u>PIT</u>	Facility ID: <u>256304</u>	API #: _____	County Name: <u>LOGAN</u>
Facility Name: <u>PROPST 1-A</u>	Latitude: <u>40.892798</u>	Longitude: <u>-103.264685</u>	
	** correct Lat/Long if needed: Latitude: _____	Longitude: _____	
QtrQtr: <u>SWSW</u> Sec: <u>26</u> Twp: <u>11N</u> Range: <u>53W</u> Meridian: <u>6</u> Sensitive Area? <u>Yes</u>			

## SITE CONDITIONS

General soil type - USCS Classifications SM

Most Sensitive Adjacent Land Use Range

Is domestic water well within 1/4 mile? No

Is surface water within 1/4 mile? No

Is groundwater less than 20 feet below ground surface? No

### **Other Potential Receptors within 1/4 mile**

National Wetlands Inventory shows unnamed ephemeral riverine 250 feet west of the SW corner of Pit. The nearest water wells permitted with the Colorado Division of Water Resources (DWR) are located approximately 0.5 miles south-southwest of the site (DWR Permit Receipt # 9045707) and 0.7 miles northwest of the site (DWR Permit Receipt # 9044315). The DWR well constructions logs report groundwater depths of 70 feet below ground surface (bgs) for DWR Permit Receipt # 9045707 (constructed in 1981) and 80 feet bgs for DWR Permit Receipt # 9044315 (constructed in 1965).

# SITE INVESTIGATION PLAN

## TYPE OF WASTE:

- |                                                    |                                                      |                                        |
|----------------------------------------------------|------------------------------------------------------|----------------------------------------|
| <input checked="" type="checkbox"/> E&P Waste      | <input type="checkbox"/> Other E&P Waste             | <input type="checkbox"/> Non-E&P Waste |
| <input checked="" type="checkbox"/> Produced Water | <input type="checkbox"/> Workover Fluids             | _____                                  |
| <input checked="" type="checkbox"/> Oil            | <input type="checkbox"/> Tank Bottoms                |                                        |
| <input type="checkbox"/> Condensate                | <input type="checkbox"/> Pigging Waste               |                                        |
| <input type="checkbox"/> Drilling Fluids           | <input type="checkbox"/> Rig Wash                    |                                        |
| <input type="checkbox"/> Drill Cuttings            | <input type="checkbox"/> Spent Filters               |                                        |
|                                                    | <input type="checkbox"/> Pit Bottoms                 |                                        |
|                                                    | <input type="checkbox"/> Other (as described by EPA) | _____                                  |

## DESCRIPTION OF IMPACT

Impacted?	Impacted Media	Extent of Impact	How Determined
UNDETERMINED	SOILS	Unknown	Pending assessment

## INITIAL ACTION SUMMARY

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

Western Operating proposes to decommission and close the unlined Propst 1A pit. Downgradient salt impacts from the pit were identified by the ECMC and are being addressed under Remediation Project 27153. Remaining produced water within the pit has been removed and disposed into the nearby Propst 1 disposal well and/or allowed to evaporate, and was documented in Field Inspection Report 709100441. Prior to conducting assessment of the pit, as described below in Proposed Soil Sampling section, the pit berms and floor material will be removed for disposal as it is suspected that earthen containment soils have been impacted during the operational lifetime of the pit. Pit berms will be removed to the native grade surface level. Soils within the pit floor will initially be excavated no deeper than 3ft-bgs for disposal of pit floor materials. Assessment and confirmation soil sampling will occur following the removal of the earthen berms and floor of the pit. Please see attached Figure 1 General Location Map, Figure 2 Proposed Soil Sample Locations, and Figure 3 Proposed Haul Truck Route for Disposal.

## PROPOSED SAMPLING PLAN

### Proposed Soil Sampling

Will soil samples be collected as part of this investigation? ( Number, type (grab/composite), analyses, and locations of samples ):

Soil borings will be conducted at a minimum of 3 locations within the pit floor area. One soil boring will be conducted at the effluent discharge area, and two borings will be within the pit floor area. Soils samples will be collected for laboratory analysis at 0.5 ft and 3 ft-bgs. One soil boring will be advanced until hand auger refusal is met, and a soil sample will be collected for laboratory analysis from the total depth; bedrock is expected at 8-15 ft-bgs.

Additionally, seven soil samples will be collected from native surface soils underneath the pit berms for submittal to laboratory analysis.

A total of 14 grab confirmation soil samples will be collected for laboratory analysis and pit removal assessment. All soil samples will be submitted for the complete Table 915-1 list of analytes in soils. See Figure 2 for proposed soil sample locations

### Proposed Groundwater Sampling

Will groundwater samples be collected as part of this investigation? ( Number, analyses, and locations of samples ):

### Proposed Surface Water Sampling

Will surface water samples be collected as part of this investigation? ( Number, analyses, and locations of samples ):

### Additional Investigative Actions

Additional alternative investigative actions described in attached Site Investigation Plan ( summary ):

# SITE INVESTIGATION REPORT

## SAMPLE SUMMARY

**Soil**

Number of soil samples collected 0  
Number of soil samples exceeding 915-1 \_\_\_\_\_  
Was the areal and vertical extent of soil contamination delineated? No  
Approximate areal extent (square feet) \_\_\_\_\_

**NA / ND**

Highest concentration of TPH (mg/kg) \_\_\_\_\_  
Highest concentration of SAR \_\_\_\_\_  
BTEX > 915-1 \_\_\_\_\_  
Vertical Extent > 915-1 (in feet) \_\_\_\_\_

**Groundwater**

Number of groundwater samples collected 0  
Was extent of groundwater contaminated delineated? No  
Depth to groundwater (below ground surface, in feet) \_\_\_\_\_  
Number of groundwater monitoring wells installed \_\_\_\_\_  
Number of groundwater samples exceeding 915-1 \_\_\_\_\_

Highest concentration of Benzene (µg/l) \_\_\_\_\_  
Highest concentration of Toluene (µg/l) \_\_\_\_\_  
Highest concentration of Ethylbenzene (µg/l) \_\_\_\_\_  
Highest concentration of Xylene (µg/l) \_\_\_\_\_  
Highest concentration of Methane (mg/l) \_\_\_\_\_

**Surface Water**

0 Number of surface water samples collected  
\_\_\_\_\_ Number of surface water samples exceeding 915-1  
If surface water is impacted, other agency notification may be required.

**OTHER INVESTIGATION INFORMATION**

Were impacts to adjacent property or offsite impacts identified?

Downgradient salt impacts from the pit were identified by the ECMC and are being addressed under Remediation Project 27153.

Were background samples collected as part of this site investigation?

A total of 16 background soil samples were collected from outside the release area reported under Remediation Project 27153 from depths ranging from 0.5 feet below ground surface (ft-bgs) to 12 ft-bgs. Laboratory analysis demonstrates that pH, arsenic, barium, and selenium concentrations exist naturally at this location above ECMC Table 915-1 Soil Screening Limits. The highest reported background level for pH (8.46) was used to establish background soil screening limits. The highest reported background levels for arsenic, barium, and selenium were multiplied by 1.25x to establish background soil screening limits of 7.25 mg/kg, 426 mg/kg and 0.325 mg/kg respectively.

Was investigation derived waste (IDW) generated as part of this investigation?

Volume of solid waste (cubic yards) \_\_\_\_\_ Volume of liquid waste (barrels) \_\_\_\_\_

Is further site investigation required?

\_\_\_\_\_

**REMEDIAL ACTION PLAN**

Does this Supplemental Form 27A include changes to a previously approved Remedial Action Plan? No

**SOURCE REMOVAL SUMMARY**

Describe how source is to be removed.

Western Operating proposes to remove the pit berms and floor soil materials for disposal, as it is suspected the earthen containment soils were impacted by E&P waste during operational lifespan. Pit berms will be removed to the native grade surface level. Soils within the pit floor will initially be excavated no deeper than 3ft-bgs for disposal of pit floor materials. If impacts are identified within native soils beneath the pit earthen containment, additional remediation or an alternative plan will be proposed via Form 27 Supplemental. The Propst 1 pit removal project area will be confined to the footprint of the historical pit. Remediation of identified impacts outside of the pit footprint are addressed under Remediation Project 27153.

From the site, it is proposed that haul trucks will travel 1.07 miles north along the access road to County Road 66 and transport the material to Pawnee Waste, LLC Landfill for disposal. Trucks will not drive off of established roads at the location, except at the "triangle" of grass near the gated entrance to the Propst sites (see attached Figure 3). Trucks may have to drive into the grass triangle in the area in order to clear the fence and gate while exiting the location. No other areas will haul trucks need to drive off of established roads, including at the project site. Impacted stockpiles of soils will be relocated to nearer the access road to be placed in disposal haul trucks - trucks will NOT drive into the historical release area to receive stockpiled soils. Please see attached Figure 3 Proposed Haul Truck route map for depictions of the discussed route. It is estimate that two to four trucks will be used to transport material at maximum on a daily basis. The proposed schedule may vary based on contractor availability and weather

**REMEDIATION SUMMARY**

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

No additional excavation or remedial action will take place at the location until an approved remedial work plan or variance is in place with ECMC.

### **Soil Remediation Summary**

**In Situ**

- \_\_\_\_\_ Bioremediation ( or enhanced bioremediation )
- \_\_\_\_\_ Chemical oxidation
- \_\_\_\_\_ Air sparge / Soil vapor extraction
- \_\_\_\_\_ Natural Attenuation
- \_\_\_\_\_ Other \_\_\_\_\_

**Ex Situ**

- \_\_\_\_\_ Excavate and offsite disposal
- \_\_\_\_\_ If Yes: Estimated Volume (Cubic Yards) \_\_\_\_\_
- \_\_\_\_\_ Name of Licensed Disposal Facility or ECMC Facility ID # \_\_\_\_\_
- \_\_\_\_\_ Excavate and onsite remediation
- \_\_\_\_\_ Land Treatment
- \_\_\_\_\_ Bioremediation (or enhanced bioremediation)
- \_\_\_\_\_ Chemical oxidation
- \_\_\_\_\_ Other \_\_\_\_\_

### **Groundwater Remediation Summary**

- \_\_\_\_\_ Bioremediation ( or enhanced bioremediation )
- \_\_\_\_\_ Chemical oxidation
- \_\_\_\_\_ Air sparge / Soil vapor extraction
- \_\_\_\_\_ Natural Attenuation
- \_\_\_\_\_ Other \_\_\_\_\_

### **GROUNDWATER MONITORING**

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.



Is additional groundwater monitoring to be conducted? \_\_\_\_\_

Operator shall comply with the ECMC 1000-Series Reclamation Requirements for all impacted and disturbed areas.

## RECLAMATION PLAN

### RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

Following remediation, the pit will be reclaimed in accordance with COGCC 1000 series rules.

Is the described reclamation complete? \_\_\_\_\_

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

Interim  Final

Did the Surface Owner provide the seed mix? \_\_\_\_\_

If YES, does the seed mix comply with local soil conservation district recommendations? \_\_\_\_\_

Did the local soil conservation district provide the seed mix? \_\_\_\_\_

### SITE RECLAMATION DATES

Proposed date of commencement of Reclamation. \_\_\_\_\_

Proposed date of completion of Reclamation. \_\_\_\_\_

## IMPLEMENTATION SCHEDULE

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

### PRIOR DATES

Date of Surface Owner notification/consultation, if required. 05/13/2024

Actual Spill or Release date, or date of discovery. \_\_\_\_\_

### SITE INVESTIGATION DATES

Date of Initial Actions described in Site Investigation Plan (start date). 06/01/2023

Proposed site investigation commencement. 08/01/2025

Proposed completion of site investigation. \_\_\_\_\_

### REMEDIAL ACTION DATES

Proposed start date of Remediation. \_\_\_\_\_

Proposed date of completion of Remediation. \_\_\_\_\_

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

Change from approved implementation schedule per Rule 913.d.(2).

Basis for change in implementation schedule:

\_\_\_\_\_

**OPERATOR COMMENT**

This Form 27 Supplemental is being submitted as a quarterly update. No activities have been conducted since the previously submitted Form 27 (Document 404131964).

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: Ryan Finley

Title: Senior Project Geologist

Submit Date: 09/26/2025

Email: rfinley@entradainc.com

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with ECMC Rules and applicable orders and is hereby approved.

ECMC Approved: Krystal Heibel

Date: 10/13/2025

Remediation Project Number: 27155

**COA Type****Description**

	<p>ECMC has processed this form as an update; no analytical was attached thus approval of this form does not imply any agreement with comments on completion of site investigation. All ongoing/unaddressed comments/COAs from previous Forms remain applicable.</p> <p>"This Form 27 Supplemental is being submitted as a quarterly update. No activities have been conducted since the previously submitted Form 27 (Document 404131964)."</p>
--	--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

1 COA

**ATTACHMENT LIST**

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

**Att Doc Num****Name**

404370492	FORM 27-SUPPLEMENTAL-SUBMITTED
-----------	--------------------------------

Total Attach: 1 Files

**General Comments****User Group****Comment****Comment Date**

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)