

# Final Reclamation Inspection

September 4, 2025

Operator: NOBLE ENERGY INC - 100322

Location ID: 462005

Inspection Document #: 718800813

Weld County, CO

Katelyn Mitchem  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Kissler  
Location ID: 462005



**Photo 1.** Photo taken of the tank battery location, facing west. Photo illustrates that final reclamation activities have taken place, but vegetation establishment does not appear to meet Rule 1004 standards and weedy annual vegetation including kochia (*Bassia scoparia*) was observed across the location.



**Photo 2.** Photo taken of the tank battery location, facing north. See comments under Photo 1.



Inspection Photos  
Location Name: Kissler  
Location ID: 462005



**Photo 3.** Photo taken of the tank battery location, facing east.  
See comments under Photo 1.



**Photo 4.** Photo taken of the tank battery location, facing south.  
See comments under Photo 1.

Inspection Photos  
Location Name: Kissler  
Location ID: 462005



**Photo 5.** Photo taken of ground cover at the tank battery location, facing east. Photo illustrates perennial grass and kochia (*Bassia scoparia*) which has recently been mowed at the time of this inspection.



**Photo 6.** Photo taken of the reference area to the location, west of the location, facing west. Photo illustrates perennial grass that has been mowed.

