

Final Reclamation Inspection

September 4, 2025

Operator: NOBLE ENERGY INC - 100322

Location ID: 329751

Inspection Document #: 718800823

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: OSTER #3-1014
Location ID: 329751



Photo 1. Google Earth Aerial Imagery from October 14, 2017 depicting the well location, access road, and associated off-location tank battery at the time of active operations.



Inspection Photos
Location Name: OSTER #3-1014
Location ID: 329751




Photo 2. Google Earth Aerial Imagery from May 2, 2024 depicting the well location, access road, and associated off-location tank battery after plugging operations. The imagery illustrates that the tank battery location is within a land use change.



Inspection Photos
Location Name: OSTER #3-1014
Location ID: 329751



Photo 3. Photo taken of the well location, facing north. Photo illustrates that the well location meets Rule 1004 standards.



Photo 4. Photo taken of the well location, facing east. See comments under Photo 3.

Inspection Photos
Location Name: OSTER #3-10I4
Location ID: 329751



Photo 5. Photo taken of the well location, facing south. See comments under Photo 3.



Photo 6. Photo taken of the well location, facing west. See comments under Photo 3.

Inspection Photos
Location Name: OSTER #3-1014
Location ID: 329751



Photo 7. Photo taken of the access road to the well location, facing north. Photo illustrates that vegetation establishment meets Rule 1004 standards.



Photo 8. Photo taken of the reference area to the well location, northwest of the location, facing northeast. Photo illustrates alfalfa cropland.



Inspection Photos
Location Name: OSTER #3-1014
Location ID: 329751



Photo 9. Photo taken of the tank battery location, facing northwest. Photo illustrates that final reclamation activities have taken place and the tank battery is now located within a land use change.



Photo 10. Photo taken of the tank battery location, facing northwest. See comments under Photo 9.

Inspection Photos
Location Name: OSTER #3-1014
Location ID: 329751



Photo 11. Photo taken of the tank battery location, facing north. See comments under Photo 9.

