

Final Reclamation Inspection

September 4, 2025

Operator: NOBLE ENERGY INC - 100322

Location ID: 421391

Inspection Document #: 718800832

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: EMBREE C #10-20D TANK
Location ID: 421391



Photo 1. Photo taken of the tank battery location, from the northeastern perimeter, facing southwest. Photo illustrates that final reclamation activities have taken place, but vegetation establishment does not meet Rule 1004 standards. Bare ground and weedy annual vegetation, including kochia (*Bassia scoparia*) and puncture vine (*Tribulus terrestris*), were observed across the location.



Photo 2. Photo taken of the tank battery location, facing south. See comments under Photo 1.



Inspection Photos
Location Name: EMBREE C #10-20D TANK
Location ID: 421391



Photo 3. Photo taken of the tank battery location, facing east. See comments under Photo 1.



Photo 4. Photo taken of the tank battery location, from the southwestern portion of the location, facing east. Photo illustrates that perennial grass has established over this portion of the location.

Inspection Photos
Location Name: EMBREE C #10-20D TANK
Location ID: 421391



Photo 5. Photo taken of the tank battery location, from the southwestern portion of the location, facing north. See comments under Photo 4.



Photo 6. Photo taken of the tank battery location, facing northwest. See comments under Photo 1.



Inspection Photos
Location Name: EMBREE C #10-20D TANK
Location ID: 421391



Photo 7. Photo taken of ground cover at the tank battery location. Photo illustrates weedy annual vegetation including puncture vine (*Tribulus terrestris*), a List C Noxious Weed species.



Photo 8. Photo taken of the reference area to the tank battery location, southwest of the location, facing west. Photo illustrates alfalfa cropland which is adjacent to the tank battery location.