

Inspection Photos

Location Name: SMITH PC AB/18-03

Location #: 419036



Photo #1

Smith PC AB 18-03 (123-32115) Wellsite

Producing | PR

**CA(s): Stained soil;
Overgrown vegetation**



Photo #2

Smith PC AB 18-03 Wellsite

Producing | PR

**CA(s): Stained soil;
Overgrown vegetation**



COLORADO


**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: SMITH PC AB/18-03

Location #: 419036



Colorado Energy & Carbon Management Commission
Weld County
+40-578527, -104-594681
185° S
2023-10-10 10:56

Photo #3

Smith PC AB 18-03 Wellsite

Producing | PR

CA(s): Stained soil;



Colorado Energy & Carbon Management Commission
Weld County
+40-578427, -104-594675
359° N
2023-10-10 10:57

Photo #4

Smith PC AB 18-03 Wellsite

Producing | PR

CA(s): Stained soil;



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Location Name: SMITH PC AB/18-03

Location #: 419036



Photo #5

Smith PC AB 18-03 Battery site

Active

Equipment documented: Fac. ID 482763



Photo #6

Smith PC AB 18-03 Battery site

Active

Wellsite(s), Battery entrance



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources