

# Final Reclamation Inspection

September 12, 2025

Operator: PDC ENERGY INC - 69175

Location ID: 471829

Inspection Document #: 718800849

Weld County, CO

Katelyn Mitchem  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: BUJALSKI 25NENE  
Location ID: 471829



**Photo 1.** Photo taken of the tank battery location, facing north. Photo illustrates that final reclamation activities have taken place, but vegetation establishment does not meet Rule 1004 standards. Weedy annual vegetation including kochia (*Bassia scoparia*) was observed across the location.



**Photo 2.** Photo taken of the tank battery location, facing southwest. See comments under Photo 1.

Inspection Photos  
Location Name: BUJALSKI 25NENE  
Location ID: 471829



**Photo 3.** Photo taken of the tank battery location, facing east. See comments under Photo 1.



**Photo 4.** Photo taken of the tank battery location, facing southeast. See comments under Photo 1.



Inspection Photos  
Location Name: BUJALSKI 25NENE  
Location ID: 471829



**Photo 5.** Photo taken of ground cover at the tank battery location. Photo illustrates weedy annual vegetation including kochia (*Bassia Scoparia*).



**Photo 6.** Photo taken of the reference area to the location, west of the location, facing west. Photo illustrates alfalfa cropland.