

Final Reclamation Inspection

September 19, 2025

Operator: NOBLE ENERGY INC - 100322

Location ID: 418737

Inspection Document #: 718800861

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: LDS D #17-17 TANK
Location ID: 418737



Photo 1. Photo taken of the tank battery location, facing south. Photo illustrates that final reclamation activities do not appear to have taken place and gravel and bare ground remain at the location.



Photo 2. Photo taken of the tank battery location, facing east. See comments under Photo 1.



Inspection Photos
Location Name: LDS D #17-17 TANK
Location ID: 418737



Photo 3. Photo taken of the tank battery location, facing north. See comments under Photo 1.



Photo 4. Photo taken of the tank battery location, facing north. Photo illustrates loose gravel remains on the northwestern portion of the location.



Inspection Photos
Location Name: LDS D #17-17 TANK
Location ID: 418737



Photo 5. Photo taken of the reference area to the location, south of the location, facing south. Photo illustrates cropland that has been harvested.

