

Final Reclamation Inspection

September 19, 2025

Operator: NOBLE ENERGY INC - 100322

Location ID: 418747

Inspection Document #: 718800869

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: LDS D #17-17
Location ID: 418747




Photo 1. Google Earth Aerial Imagery from October 7, 2012 depicting the well location prior to location abandonment.

Inspection Photos
Location Name: LDS D #17-17
Location ID: 418747




Photo 2. Google Earth Aerial Imagery from September 6, 2013 depicting the well location after location abandonment.

Inspection Photos
Location Name: LDS D #17-17
Location ID: 418747



Photo 3. Photo taken of the abandoned well location, facing north. Photo illustrates that there is no evidence of oil and gas disturbance at the location and based on records the well was never drilled.



Photo 4. Photo taken of the abandoned well location, facing east. See comments under Photo 3.

Inspection Photos
Location Name: LDS D #17-17
Location ID: 418747



Photo 5. Photo taken of the abandoned well location, facing south. See comments under Photo 3.



Photo 6. Photo taken of the abandoned well location, facing west. See comments under Photo 3.