

# Final Reclamation Inspection

September 19, 2025

Operator: NOBLE ENERGY INC - 100322

Location ID: 418733

Inspection Document #: 718800876

Weld County, CO

Katelyn Mitchem  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: LDS D #17-24D TANK  
Location ID: 418733



**Photo 1.** Photo taken of the tank battery location, facing east. Photo illustrates that final reclamation activities do not appear to have taken place. Debris, gravel, weedy annual vegetation, and bare ground were observed across the location.



**Photo 2.** Photo taken of the tank battery location, facing northeast. See comments under Photo 1.

Inspection Photos  
Location Name: LDS D #17-24D TANK  
Location ID: 418733



**Photo 3.** Photo taken of the tank battery location, facing north. Photo illustrates weedy annual vegetation, including kochia (*Bassia scoparia*) and fencing around holes dug into the ground.



**Photo 4.** Photo taken of the tank battery location, facing east. Photo illustrates that fencing is in disrepair.

Inspection Photos  
Location Name: LDS D #17-24D TANK  
Location ID: 418733



**Photo 5.** Photo taken of the tank battery location, facing northeast. Photo illustrates fencing that is in disrepair.



**Photo 6.** Photo taken of the tank battery location, facing south. Photo illustrates bare ground and gravel remain across this portion of the location.



Inspection Photos  
Location Name: LDS D #17-24D TANK  
Location ID: 418733



**Photo 7.** Photo taken of the tank battery location, facing northeast. See comments under Photo 6.



**Photo 8.** Photo taken of the tank battery location, facing northwest. Photo illustrates debris that remains on the location.

Inspection Photos  
Location Name: LDS D #17-24D TANK  
Location ID: 418733



**Photo 9.** Photo taken of ground cover at the location. Photo illustrates cut cables that remain in the ground at the location.



**Photo 10.** Photo taken of the tank battery location. See comments under Photo 9.

Inspection Photos  
Location Name: LDS D #17-24D TANK  
Location ID: 418733



**Photo 11.** Photo taken of the reference area to the location, north of the location, facing east. Photo illustrates cropland that has been harvested.

