

Final Reclamation Inspection

September 19, 2025

Operator: NOBLE ENERGY INC - 100322

Location ID: 415721

Inspection Document #: 718800894

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: GUTTERSEN D #16-28
Location ID: 415721



Photo 1. Photo taken of the well location, facing north. Photo illustrates that final reclamation activities have taken place, with evidence of drill row seeding, but vegetation establishment does not meet Rule 1004 standards. Weedy annual vegetation including russian thistle (*Salsola tragus*) was observed across the location.



Photo 2. Photo taken of the well location, facing east. See comments under Photo 1.

Inspection Photos
Location Name: GUTTERSEN D #16-28
Location ID: 415721



Photo 3. Photo taken of the well location, facing south. See comments under Photo 1.



Photo 4. Photo taken of the well location, facing west. See comments under Photo 1.

Inspection Photos
Location Name: GUTTERSEN D #16-28
Location ID: 415721



Photo 5. Photo taken of the access road to the well location, facing south, towards the location. Photo illustrates that final reclamation activities have taken place, with evidence of drill row seeding, but vegetation has not established to Rule 1004 standards.



Photo 6. Photo taken of the access road to the well location, facing north, away from the location. See comments under Photo 5.

Inspection Photos
Location Name: GUTTERSEN D #16-28
Location ID: 415721



Photo 7. Photo taken of ground cover at the well location. Photo illustrates evidence of drill rows from seeding and weedy annual vegetation including russian thistle (*Salsola tragus*).



Photo 8. Photo taken of the reference area to the well location, northeast of the location, facing east. Photo illustrates perennial grass vegetation, prairie sunflower, and weedy annual vegetation.