

Final Reclamation Inspection

September 19, 2025

Operator: NOBLE ENERGY INC - 100322

Location ID: 328312

Inspection Document #: 718800903

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: GITTLEIN-UPRC #9-12
Location ID: 328312



Photo 1. Photo taken of the well location, facing north. Photo illustrates that final reclamation activities have taken place, but vegetation establishment does not meet Rule 1004 standards. Weedy annual vegetation including kochia (*Bassia scoparia*) and cheatgrass (*Bromus tectorum*), a List C Noxious Weed species, were observed across the location.



Photo 2. Photo taken of the well location, facing east. See comments under Photo 1.

Inspection Photos
Location Name: GITTLEIN-UPRC #9-12
Location ID: 328312



Photo 3. Photo taken of the well location, facing south. See comments under Photo 1.



Photo 4. Photo taken of the well location, facing west. See comments under Photo 1.

Inspection Photos
Location Name: GITTLEIN-UPRC #9-12
Location ID: 328312



Photo 5. Photo taken ground cover at the well location, facing south. Photo illustrates weedy annual vegetation including cheatgrass (*Bromus tectorum*), a List C Noxious Weed species, and kochia (*Bassia scoparia*).



Photo 6. Photo taken of the tank battery location, facing southeast. Photo illustrates that final reclamation activities do not appear to have taken place as bare ground, gravel, and weedy annual vegetation were observed across the location. Midstream equipment also remains at the location, see Photo 8.

Inspection Photos
Location Name: GITTLEIN-UPRC #9-12
Location ID: 328312



Photo 7. Photo taken of the tank battery location, facing south. See comments under Photo 6.



Photo 8. Photo taken of the tank battery location, facing west. Photo illustrates that a meter house remains at the location.



Inspection Photos
Location Name: GITTLEIN-UPRC #9-12
Location ID: 328312



Photo 9. Photo taken of the tank battery location, facing north. See comments under Photo 6.



Photo 10. Photo taken of the reference area, south of the location, facing south. Photo illustrates perennial grass and weedy annual vegetation.

