

Inspection Photos
Location Name: Whitehead 12-16
Location ID: 322159



Pic 1 rig

Pic 2 temporary pit

Inspection Photos
Location Name: Whitehead 12-16
Location ID: 322159



Pic 3 temporary pit

Pic 4 temporary pit

Inspection Photos
Location Name: Whitehead 12-16
Location ID: 322159



Pic 5 tubing on locataion needs to be removed.

Pic 6 Casing on location needs to be removed

Inspection Photos
Location Name: Whitehead 12-16
Location ID: 322159



Pic 6 Tubing on location needs to be removed

Pic 7 temporary pit is leaking

Inspection Photos
Location Name: Whitehead 12-16
Location ID: 322159



Pic 8 temporary pit

Pic 9 casing on location needs to be removed

Inspection Photos
Location Name: Whitehead 12-16
Location ID: 322159



Pic 9 Accumulator, tanks

Pic 10 trenching from wellhead to temporary pit

Inspection Photos
Location Name: Whitehead 12-16
Location ID: 322159



Pic 11 Trenching from wellhead to temporary pit and tank hoses

Pic 12 Tank, trencher

Inspection Photos
Location Name: Whitehead 12-16
Location ID: 322159



Pic 13 temporary pit is leaking

Pic 14 Temporary pit

Inspection Photos
Location Name: Whitehead 12-16
Location ID: 322159



Pic 15 wellhead sign