

Operator: HIGHPOINT OPERATING CORPORATION

Location Name: NEELY-N39N17W 18SWSW

Loc ID: 322140

Inspection: 714002182



Exhibit A



Exhibit B



Exhibit C



Exhibit D

CA: Russian olive observed at the center of the project area. Comply with rule 1004.e, treat/remove weeds

CA Resolution: Operator has removed the small Russian olive tree/s removed from this location in order to comply with Rule 606.

