

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
404380875

Receive Date:

---

Report taken by:

**Site Investigation and Remediation Workplan (Supplemental Form)**

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by ECMC is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27.

This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Closure request is not available for an Initial Site Investigation and Remediation Workplan.

**OPERATOR INFORMATION**

Name of Operator: NOBLE ENERGY INC	Operator No: 100322	<b>Phone Numbers</b>
Address: 1099 18TH STREET SUITE 1500		Phone: (970) 304-5000
City: DENVER State: CO Zip: 80202		Mobile: ( )
Contact Person: Kristofer Shephard	Email: rbueuf27@chevron.com	

**PROJECT, PURPOSE & SITE INFORMATION**

**PROJECT INFORMATION**

Remediation Project #: 29144 Initial Form 27 Document #: 403387088

**PURPOSE INFORMATION**

- Rule 913.c.(1): Pit or Cuttings Trench closure.
- Rule 913.c.(2): Buried or partially buried vessel closure, which will be by removal.
- Rule 913.c.(3): Remediation of Spill and Releases pursuant to Rule 912.
- Rule 913.c.(4): Land treatment of Oily Waste pursuant to Rule 905.e.
- Rule 913.c.(5): Closure of Centralized E&P Waste Management Facilities pursuant to Rule 907.h.
- Rule 913.c.(6): Remediation of impacted Groundwater pursuant to Rule 915.e.(3).D, and the contaminant concentrations in Table 915-1.
- Rule 913.c.(7): Investigation and remediation of natural gas in soil or Groundwater.
- Rule 913.c.(8): When requested by the Director due to any potential risk to soil, Groundwater, or surface water.
- Rule 913.c.(9): Decommissioning of Oil and Gas Facilities.
- Rule 913.g: Changes of Operator.
- Rule 915.b: Request to leave elevated inorganics in situ.
- Other: \_\_\_\_\_

**SITE INFORMATION**

Yes Multiple Facilities

Facility Type: WELL	Facility ID: _____	API #: 123-09739	County Name: WELD
Facility Name: VERN MARSHALL 1	Latitude: 40.267290	Longitude: -104.694090	
** correct Lat/Long if needed: Latitude: _____		Longitude: _____	
QtrQtr: NWSW	Sec: 32	Twp: 4N	Range: 65W Meridian: 6 Sensitive Area? Yes
Facility Type: SPILL OR RELEASE	Facility ID: 485132	API #: _____	County Name: WELD
Facility Name: Vern Marshall 1	Latitude: 40.266256	Longitude: -104.692391	
** correct Lat/Long if needed: Latitude: _____		Longitude: _____	
QtrQtr: NWSW	Sec: 32	Twp: 4N	Range: 65W Meridian: 6 Sensitive Area? Yes

## **SITE CONDITIONS**

General soil type - USCS Classifications SW \_\_\_\_\_

Most Sensitive Adjacent Land Use Crop Land \_\_\_\_\_

Is domestic water well within 1/4 mile? Yes \_\_\_\_\_

Is surface water within 1/4 mile? Yes \_\_\_\_\_

Is groundwater less than 20 feet below ground surface? No \_\_\_\_\_

### **Other Potential Receptors within 1/4 mile**

Riverine 0.18mi SE, 0.22mi NW  
Freshwater Pond 0.09mi NW  
Pond 0.14mi SE  
Residence 0.16mi NW, 0.23mi S, 0.17/0.19/0.25mi SW  
Well located within livestock pen  
Farm structure 0.07/0.08/0.10/0.12/0.14/0.25mi NW

# SITE INVESTIGATION PLAN

## **TYPE OF WASTE:**

- |  |  |  |
|--|--|--|
| <input checked="" type="checkbox"/> E&P Waste      | <input type="checkbox"/> Other E&P Waste             | <input type="checkbox"/> Non-E&P Waste |
| <input checked="" type="checkbox"/> Produced Water | <input type="checkbox"/> Workover Fluids             | _____                                  |
| <input checked="" type="checkbox"/> Oil            | <input type="checkbox"/> Tank Bottoms                |  |
| <input checked="" type="checkbox"/> Condensate     | <input type="checkbox"/> Pigging Waste               |  |
| <input type="checkbox"/> Drilling Fluids           | <input type="checkbox"/> Rig Wash                    |  |
| <input type="checkbox"/> Drill Cuttings            | <input type="checkbox"/> Spent Filters               |  |
|  | <input type="checkbox"/> Pit Bottoms                 |  |
|  | <input type="checkbox"/> Other (as described by EPA) | _____                                  |

## **DESCRIPTION OF IMPACT**

Impacted?	Impacted Media	Extent of Impact	How Determined
UNDETERMINED	GROUNDWATER	NA	Lab analysis and field screening, if encountered
Yes	SOILS	Refer to Tables & Figures	Lab analysis and field screening

## **INITIAL ACTION SUMMARY**

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

Pursuant to ECMC Rule 911 a site investigation was conducted pertaining to the MARSHALL VERN 1 wellhead cut and cap and flowline removal. The wellhead was cut and capped per ECMC rules. The flowline was partially abandoned in place and the Form 44 Flowline Abandonment Notice Document Number is included under Related Forms. Additionally, soil samples were field screened at the N-E-S-W sides of the wellhead cut and cap excavation area, and soil samples were taken at the base of the wellhead excavation and at either end of the flowline during abandonment activities.

## **PROPOSED SAMPLING PLAN**

### **Proposed Soil Sampling**

Will soil samples be collected as part of this investigation? ( Number, type (grab/composite), analyses, and locations of samples ):

A grab soil sample was collected at the base of the cut and cap excavation area or the area showing the highest degree of impact during field screening activities at the wellhead excavation. Additionally, soil samples were field screened at the N-E-S-W sides of the wellhead. Soil samples were taken at either end of the flowline during abandonment activities. Soil samples were analyzed by a certified laboratory for TPH (total volatile [C6-C10] and extractable [C10-C36] hydrocarbons) organic compounds in soil per ECMC Table 915-1, metals in soil per ECMC Table 915-1, EC, SAR, pH, and boron. All samples collected were analyzed by a certified laboratory using ECMC-approved laboratory analysis methods.

### **Proposed Groundwater Sampling**

Will groundwater samples be collected as part of this investigation? ( Number, analyses, and locations of samples ):

If groundwater it encountered during the site investigation, grab groundwater samples will be collected and analyzed for all organic and inorganic compounds per ECMC Table 915-1.

### **Proposed Surface Water Sampling**

Will surface water samples be collected as part of this investigation? ( Number, analyses, and locations of samples ):

## **Additional Investigative Actions**

Additional alternative investigative actions described in attached Site Investigation Plan ( summary ):

Visual inspection of the wellhead and flowline areas occurred during abandonment activities. Field personnel field screened all disturbed areas using visual and olfactory senses to determine if laboratory confirmation sampling was required. The ECMC Flowline Closure and Wellhead Closure Checklists were utilized and filled out during the abandonment process. Detailed summaries of the wellhead and flowline decommissioning activities, including field notes, site photos, figures, and laboratory analytical results are were submitted to the ECMC attached to Form 27 Document #403683172.

# SITE INVESTIGATION REPORT

## **SAMPLE SUMMARY**

**Soil**

Number of soil samples collected 11

Number of soil samples exceeding 915-1 1

Was the areal and vertical extent of soil contamination delineated? No

Approximate areal extent (square feet) 1200

**NA / ND**

-- Highest concentration of TPH (mg/kg) 611

NA Highest concentration of SAR         

BTEX > 915-1 No

Vertical Extent > 915-1 (in feet) 7

**Groundwater**

Number of groundwater samples collected 0

Was extent of groundwater contaminated delineated? Yes

Depth to groundwater (below ground surface, in feet)         

Number of groundwater monitoring wells installed         

Number of groundwater samples exceeding 915-1         

Highest concentration of Benzene (µg/l)         

Highest concentration of Toluene (µg/l)         

Highest concentration of Ethylbenzene (µg/l)         

Highest concentration of Xylene (µg/l)         

Highest concentration of Methane (mg/l)         

**Surface Water**

0 Number of surface water samples collected

         Number of surface water samples exceeding 915-1

If surface water is impacted, other agency notification may be required.

**OTHER INVESTIGATION INFORMATION**

Were impacts to adjacent property or offsite impacts identified?

Were background samples collected as part of this site investigation?

Ten background soil samples were collected from five soil borings (BG01-BG05) near the flowline and analyzed for arsenic, pH, SAR, and EC. Background soil samples were collected from depths ranging between 4 to 8 feet below ground surface (ft bgs) and the lithology between the site and background locations were observed to be sandy clays.  
  
On 9/30/2025, six background soil samples were collected from two discrete locations (BKG06-BKG07) near the flowline and analyzed for metals in soil per ECMC Table 915-1, pH, SAR, EC, and boron. Background soil samples were collected from depths ranging between 2 to 6 feet below ground surface (ft bgs). Background sampling results are currently pending, and will be submitted on a subsequent Form 27.

Was investigation derived waste (IDW) generated as part of this investigation?

Volume of solid waste (cubic yards)         

Volume of liquid waste (barrels)         

Is further site investigation required?

Remedial excavation activities occurred between 10/02/2025 through 10/06/2025 to address the organic compound exceedances observed at sample locations BH02@4' and FL01-B@4'. Confirmation soil samples were collected from the final excavation extents and analyzed for full ECMC Table 915-1 constituents. The results of the remedial excavations are currently pending and will be submitted on a subsequent Form 27.

**REMEDIAL ACTION PLAN**

Does this Supplemental Form 27A include changes to a previously approved Remedial Action Plan? No

**SOURCE REMOVAL SUMMARY**

Describe how source is to be removed.

Between 10/2/2025 and 10/6/2025, approximately 40 cubic yards of source material was excavated and transported off-site for disposal at the Waste Management Buffalo Ridge Landfill in Keenesburg, CO under Noble waste manifests.

**REMEDIATION SUMMARY**

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

A Site Assessment was conducted on 1/3/2024 to delineate impacted media, during which five soil borings were advanced. BH01 was advanced at the same location as the waste characterization sample FL01-B@4' to vertically delineate impacts at that location. BH02-BH05 were advanced surrounding BH01 to vertically and laterally delineate impacts identified at FL01-B@4'. Soil samples were collected and analyzed for Organic compounds in soil per ECMC Table 915-1, TPH, arsenic, pH, EC, and SAR per the amended sampling plan that was approved under ECMC document number 403683172. Groundwater was encountered during this assessment, however, due to the depth of groundwater being present at the terminus of the soil borings and not in contact with impacted material, no groundwater samples were able to be collected. Soil boring sample BH01@4' was collected from the same location as waste characterization samples FL01-B@4'. The organic compounds exceeding ECMC Table 915-1 standards identified during decommissioning at FL01-B@4' was not repeated by resample location BH01@4', but a benzo(a)anthracene exceedance was observed at BH02@4'.

Remedial excavation activities occurred between 10/2/2025 and 10/6/2025 to address the organic compound exceedances observed at sample locations BH02@4' and FL01-B@4'. Confirmation soil samples were collected from the final excavation extents and analyzed for full ECMC Table 915-1 constituents. The final laboratory results from the remedial excavations remain pending and will be submitted on a subsequent Form 27.

**Soil Remediation Summary**

In Situ

Ex Situ

\_\_\_\_\_ Bioremediation ( or enhanced bioremediation )

\_\_\_\_\_ Yes Excavate and offsite disposal

\_\_\_\_\_ Chemical oxidation

\_\_\_\_\_ If Yes: Estimated Volume (Cubic Yards) \_\_\_\_\_ 40

\_\_\_\_\_ Air sparge / Soil vapor extraction

\_\_\_\_\_ Name of Licensed Disposal Facility or ECMC Facility ID # \_\_\_\_\_

\_\_\_\_\_ Natural Attenuation

\_\_\_\_\_ Excavate and onsite remediation

\_\_\_\_\_ Other \_\_\_\_\_

\_\_\_\_\_ Land Treatment

\_\_\_\_\_ Bioremediation (or enhanced bioremediation)

\_\_\_\_\_ Chemical oxidation

\_\_\_\_\_ Other \_\_\_\_\_

**Groundwater Remediation Summary**

\_\_\_\_\_ Bioremediation ( or enhanced bioremediation )

\_\_\_\_\_ Chemical oxidation

\_\_\_\_\_ Air sparge / Soil vapor extraction

\_\_\_\_\_ Natural Attenuation

\_\_\_\_\_ Other \_\_\_\_\_

**GROUNDWATER MONITORING**

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

Groundwater was encountered during the 01/03/2024 site assessment, however, due to the depth of groundwater being present at the terminus of the soil borings and not in contact with impacted material, no groundwater samples were able to be collected.

Groundwater was not encountered during initial decommissioning or remedial excavation activities.

# REMEDIATION PROGRESS UPDATE

## PERIODIC REPORTING

### Approved Reporting Schedule:

Quarterly     Semi-Annually     Annually     Other

### Request Alternative Reporting Schedule:

Semi-Annually     Annually     Other

Rule 913.e:

After initial approval of a Form 27, the Operator will provide quarterly update reports in a Supplemental Form 27 to document progress of site investigation and remediation, unless an alternative reporting schedule has been requested by the Operator and approved by the Director. The Director may request a more frequent reporting schedule based on site-specific conditions.

**Report Type:**     Groundwater Monitoring     Land Treatment Progress Report     O&M Report

Other Confirmation Sample Summary & Fourth Quarter 2025  
Timeline update \_\_\_\_\_

## Adequacy of Operator's General Liability Insurance and Financial Assurance

Describe the adequacy of the Operator's general liability insurance and Financial Assurance to fully address the anticipated costs of Remediation, including the estimated remaining cost for this project (below).

If this information has been provided on a Form 27 within the last 12 months, provide the Document Number of that form.

Noble intends to directly address the costs of remediation at the locations as part of our asset retirement obligation process and operations. Noble has general liability insurance (policies MWZZ316714 and MWZX316724) and financial assurance in compliance with ECMC rules. Records are available on the ECMC's website. The cost for remediation is an estimate only, costs may change upwards or downward based on site-specific information. Noble makes no representation or guarantees as to the accuracy of the estimate.

Operator anticipates the remaining cost for this project to be: \$ 50000 \_\_\_\_\_

## WASTE DISPOSAL INFORMATION

Was E&P waste generated as part of this remediation? Yes

Describe beneficial use, if any, of E&P Waste derived from this remediation project:

N/A

Volume of E&P Waste (solid) in cubic yards \_\_\_\_\_ 40

E&P waste (solid) description Impacted soils

ECMC Disposal Facility ID #, if applicable: \_\_\_\_\_

Non-ECMC Disposal Facility: Buffalo Ridge Landfill - Keenesburg, CO

Volume of E&P Waste (liquid) in barrels \_\_\_\_\_ 0

E&P waste (liquid) description \_\_\_\_\_

ECMC Disposal Facility ID #, if applicable: \_\_\_\_\_

Non-ECMC Disposal Facility: \_\_\_\_\_

# REMEDIATION COMPLETION REPORT

## REMEDIATION COMPLETION SUMMARY

Is this a Final Closure Request for this Remediation Project? No

If YES:

Compliant with Rule 913.h.(1).

Compliant with Rule 913.h.(2).

Compliant with Rule 913.h.(3).

Do all soils meet Table 915-1 standards? \_\_\_\_\_

Does the previous reply indicate consideration of background concentrations? \_\_\_\_\_

Does Groundwater meet Table 915-1 standards? \_\_\_\_\_

Is additional groundwater monitoring to be conducted? \_\_\_\_\_

Operator shall comply with the ECMC 1000-Series Reclamation Requirements for all impacted and disturbed areas.

## RECLAMATION PLAN

### RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

Reclamation will be in accordance with ECMC 1000 Series Rules.

Is the described reclamation complete? No \_\_\_\_\_

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

Interim

Final

Did the Surface Owner provide the seed mix? \_\_\_\_\_

If YES, does the seed mix comply with local soil conservation district recommendations? \_\_\_\_\_

Did the local soil conservation district provide the seed mix? \_\_\_\_\_

### SITE RECLAMATION DATES

Proposed date of commencement of Reclamation. 07/26/2023

Proposed date of completion of Reclamation. 12/31/2027

## IMPLEMENTATION SCHEDULE

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

### PRIOR DATES

Date of Surface Owner notification/consultation, if required. 12/27/2022

Actual Spill or Release date, or date of discovery. 09/20/2023

### SITE INVESTIGATION DATES

Date of Initial Actions described in Site Investigation Plan (start date). 07/26/2023

Proposed site investigation commencement. 10/02/2025

Proposed completion of site investigation. 10/06/2025

### REMEDIAL ACTION DATES

Proposed start date of Remediation. 10/06/2025

Proposed date of completion of Remediation. 10/06/2027

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

Change from approved implementation schedule per Rule 913.d.(2).

Basis for change in implementation schedule:

The implementation schedule has been changed to provide another quarter to summarize the analytical results and propose additional site actions as necessary. The ECMC will be notified of any updates to the implementation schedule in a subsequent Form 27.

**OPERATOR COMMENT**

This Form 27 is being submitted to include the remedial excavation summary for the Vern Marshall 1 Tank Battery (Rem # 29144) location.

Remedial excavation activities occurred between 10/2/2025 and 10/6/2025 to address the organic compound exceedances observed at sample locations BH02@4' and FL01-B@4'. Confirmation soil samples were collected from the final excavation extents and analyzed for full ECMC Table 915-1 constituents. The final laboratory results from the remedial excavations remain pending and will be submitted on a subsequent Form 27.

On 9/30/2025, six background soil samples were collected from two discrete locations (BKG06-BKG07) near the flowline and analyzed for metals in soil per ECMC Table 915-1, pH, SAR, EC, and boron. Background soil samples were collected from depths ranging between 2 to 6 feet below ground surface (ft bgs). Background sampling results are currently pending, and will be submitted on a subsequent Form 27.

The implementation schedule was updated due to the completion of source removal activities on 10/06/2025 as detailed in the Site Investigation Report section of this Form 27. The final analytical reports from excavation soil samples remain pending, and will be submitted on a subsequent Form 27.

Pursuant to Rule 913.e, quarterly reporting will be conducted until closure criteria are achieved for the remediation project. The results of the supplemental site investigation will be submitted on a subsequent Form 27.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: Ben Wagner

Title: Environmental Consultant

Submit Date: \_\_\_\_\_

Email: tas-chevron-4@tasman-geo.com

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with ECMC Rules and applicable orders and is hereby approved.

ECMC Approved: \_\_\_\_\_

Date: \_\_\_\_\_

Remediation Project Number: 29144

**COA Type**

**Description**

0 COA	
-------	--

**ATTACHMENT LIST**

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

**Att Doc Num**

**Name**

404390860	SOIL SAMPLE LOCATION MAP
-----------	--------------------------

Total Attach: 1 Files

**General Comments**

**User Group**

**Comment**

**Comment Date**

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)