

## Inspection Photos

Location Name: DILLARD USX AB/03-09P

Location #: 310783



Photo #1

Dillard USX AB 03-09P (123-26969) Wellsite

Producing | PR



Photo #2

Dillard USX AB 03-09P Battery site

Active

**Equipment documented: Loc. ID 310783**

Formerly served: Dillard USX AB 03-15P, 03-16

Plugged & Abandoned | PA



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

## Inspection Photos

Location Name: DILLARD USX AB/03-09P

Location #: 310783



**Photo #3**

**Dillard USX AB 03-09P** Battery site

**Active**

*Well(s) site(s), Battery entrance*



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources