

Inspection Photos

Location Name: Dillard USX AB/03-08P

Location #: 415346



Photo #1

Dillard USX AB 03-08P (123-31060) Wellsite

Plugged & Abandoned | PA

Cut / Capped

~ 5 yds.



Photo #2

Dillard USX AB 03-07P, 03-05P, 03-06P, 03-08P

Battery site

Abandoned: ALL Equipment Removed

Formerly served: 4: Wellsite(s);

Plugged & Abandoned | PA



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources