

# Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 262-1 Pad

Location #: 324325



Photo # 4951 From entrance to location



Photo # 4952 Location

# Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 262-1 Pad

Location #: 324325



Photo # 4953 Location




Photo # 4954 Location

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 262-1 Pad

Location #: 324325



**Photo # 4955 Burner & fire tube open to entry by wildlife  
/wildlife hazard**



**Photo # 4956 Observed compliance issue addressed by QB  
employee during inspection**

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 262-1 Pad

Location #: 324325




Photo # 4957 Battery sign contains inaccurate information