

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 251-36 Pad

Location #: 324332



Photo # 5053 From entrance to location




Photo # 5054 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 251-36 Pad

Location #: 324332



Photo # 5055 Location




Photo # 5056 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 251-36 Pad

Location #: 324332




Photo # 5057 Location



Photo # 5058 Weeds/undesirable plant species in secondary containment

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 251-36 Pad

Location #: 324332



Photo # 5059 Weeds/undesirable plant species in secondary containment



Photo # 5060 Weeds/undesirable plant species in secondary containment

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 251-36 Pad

Location #: 324332



Photo # 5061 Weeds/undesirable plant species in secondary containment



Photo # 5062 Weeds/undesirable plant species in secondary containment

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 251-36 Pad

Location #: 324332



Photo # 5063 Weeds/undesirable plant species in secondary containment



Photo # 5064 Weeds & debris

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 251-36 Pad

Location #: 324332



Photo # 5065 Open ended pipe near separator/wildlife hazard/available for entry by wildlife



Photo # 5066 Open ended pipe near separator/wildlife hazard/available for entry by wildlife

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 251-36 Pad

Location #: 324332



Photo # 5067 Improperly marked deadman

Photo # 5068 Same improperly marked deadman

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 251-36 Pad

Location #: 324332



Photo # 5069 Unmarked deadman



Photo # 5070 Same unmarked deadman

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 251-36 Pad

Location #: 324332



Photo # 5071 Unmarked deadman



Photo # 5072 Same unmarked deadman

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 251-36 Pad

Location #: 324332



Oct 8, 2025 at 3:34:53 PM
+39.486184, -108.467437
138° SE



Oct 8, 2025 at 3:35:02 PM
+39.486184, -108.467437
138° SE

Photo # 5073 Unmarked deadman

Photo # 5074 Same unmarked deadman

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 251-36 Pad

Location #: 324332



Photo # 5075 Same unmarked deadman

Photo # 5076 Debris